

Appendix B

Wetland Information



Report Date: September 6, 2022 (last revised February 1, 2023)

Prepared For: Ms. Mary Anne Antonellis, Director

M.N. Spear Memorial Library

10 Cooleyville Road

PO Box 256

Shutesbury, MA 01072

Site Address: 66 Leverett Road

Shutesbury, Massachusetts 01072

Delineation Date(s): August 5 and 16, November 10 and 28, 2022

Regulated & Protected Resource Areas¹

Bank	
☐ Land Under Water Bodies and Waterways	☐ Land Subject to Flooding
Riverfront Area	□ Buffer Zone
☐ Isolated Vegetated Wetlands (IVW)	☐ Estimated Habitats of Rare Wildlife
☐ Priority Habitats of Rare Species	☐ Vernal Pool (Certified and/or Potential)

Table 1
Summary of Wetland Delineation Flag Series

Flag Series	Flag Number	Resource Area Type	Jurisdictional Under the MAWPA and Shutesbury Wetlands Bylaw	Description
1	1A-100 → 1A-133	BVW	Yes	Palustrine Forested Wetland (PFO) and mowed Palustrine Emergent Wetland (PEM)
2	2A-100 → 2A-106	BVW	Yes	PFO
3	3A-100 → 3A-118 3B-100 → 3B-113	BVW	Yes	PEM and PFO
4	4A-100 → 4A-105	IVW	No	PEM in access route
5	5A-100 → 5A-103	IVW	No	PEM in access route
6	6A-100 → 6A-104	IVW	No	PEM in access route
7	7A-100 → 7A-107	IVW	No	PEM adjacent to access route

1550 Main Street Suite 400 Springfield, MA 01103 † 413.452.0445 800.286.2469 f 860.533.5143

www.fando.com

California

Connecticut

Maine

Massachusetts

New Hampshire

Rhode Island

Vermont

¹Under the Massachusetts Wetlands Protection Act (MAWPA), Shutesbury General Wetlands Protection Bylaw (Shutesbury Wetlands Bylaw), and Massachusetts Endangered Species Act (MESA)



Inland resource areas were delineated in accordance with applicable local, state, and federal statutes, as detailed within the Resource Area Description. This delineation does not constitute an official wetland boundary until such time as it is accepted and approved by local, state, or federal regulatory agencies.

The wetland delineation was conducted by:

April Doroski, PWS, CPSS Water Resources and Climate Resilience Specialist

1550 Main Street Suite 400 Springfield, MA 01103 † 413.452.0445 800.286.2469 f 860.533.5143

www.fando.com

California
Connecticut
Maine

Massachusetts

New Hampshire

Rhode Island Vermont ¹Under the Massachusetts Wetlands Protection Act (MAWPA), Shutesbury General Wetlands Protection Bylaw (Shutesbury Wetlands Bylaw), and Massachusetts Endangered Species Act (MESA)



September 6, 2022 (last revised February 1, 2023)

ATTACHMENTS

A Figures

- o USGS Topographic Map (Figure 1)
- o Wetland Delineation Overview (Figure 2)
- o Wetland Flag Locations (Figure 3)
- o Wetland Delineation Change Map (Figure 4)

B Site Photographs

C Wetland Determination Data Forms - Northcentral and Northeast Region

- o BVWs 1, 2, and 3
- o Upland Forms

D FEMA Information

o FEMA FIRMette (Panel No. 250128 0001 0020, effective June 18, 1980)

E NRCS Custom Soil Resource Report

O Custom Soil Resource Report of Franklin County, Massachusetts (August 30, 2022)



September 6, 2022 (last revised February 1, 2023) Page 1

Resource Area Description

1.1 Introduction

On August 5 and 26, 2022, a Fuss & O'Neill Inc. wetland and soil scientist performed a wetland resource area delineation within the Parcel O-32 at 66 Leverett Road ("Subject Parcel") located in Shutesbury, Massachusetts. The results of the wetland delineation for the front portion of the Subject Parcel (approximately 1,450 feet from Leverett Road) are discussed below. Refer to the figures in Attachment A for the limits of the ANRAD Review Area.

The purpose of this investigation was to identify and delineate the jurisdictional limits of regulated and protected resource areas as defined by the Wetlands Protection Act (M.G.L. c. 131 § 40) and its implementing regulations (310 CMR 10.00), the 1987 Corps of Engineers Wetlands Delineation Manual, the Regional Supplement to the Corps of Engineers Wetlands Delineation Manual: Northcentral and Northeast Region (2012), and the Shutesbury General Wetlands Protection Bylaw and its implementing regulations. This report also includes an assessment of areas protected under the Massachusetts Endangered Species Act (M.G.L. c. 131A).

As part of the Peer-Review process for the Abbreviated Notice of Resource Area Delineation, subsequent investigations were conducted and wetland boundaries updated and new isolated wetlands (non-jurisdictional) were delineated. These subsequent investigations occurred on November 10 and 28, 2022. Revisions were made based on comments from the Peer-Reviewer, Stockman Associates, LLC. The results of the August delineation and November investigations are described below.

This report provides a summary of wetland resource areas within the ANRAD Review Area and includes figures (*Attachment A*), site photographs (*Attachment B*), wetland determination data forms (*Attachment C*), and supplemental information (*Attachments D* and *E*).

1.2 Methodology of Resource Area Delineation

The wetland delineation was conducted in conformance with local, state, and federal regulations and guidelines including:

- Massachusetts Wetlands Protection Act ("MAWPA"; M.G.L. c. 131, § 40), its implementing regulations set forth at 310 CMR 10.00
- Massachusetts Department of Environmental Protection (MassDEP) Delineating Bordering Vegetated Wetlands Under the Massachusetts Wetlands Protection Act (March 1995)
- Corps of Engineers Wetlands Delineation Manual, Technical Report Y-87-1 (January 1987)



September 6, 2022 (last revised February 1, 2023) Page 2

- Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northcentral and Northeast Region (January 2012)
- Field Indicators for Identifying Hydric Soils in New England in New England (Version 4, April 2019)
- Town of Shutesbury General Wetlands Protection Bylaw (Shutesbury Wetlands Bylaw) and associated Regulations under the General Wetlands Protection Bylaw

Due to the disturbed nature of BVWs 1 and 2 and IVWs 4, 5, and 6, these wetlands were delineated in accordance with methodologies for altered areas including:

- 310 CMR 10.55(2)(c)3
- "Delineating BVWs where hydrology or vegetation has been altered" Section, Delineating Bordering Vegetated Wetlands Under the Massachusetts Wetlands Protection Act Handbook, MassDEP, 1995
- "Section 5 Difficult Situations" of the Regional Supplement to the Corps of Engineers Wetland Delineation Manual: Northcentral and Northeast Region, ed. J. S. Wakeley, R. W. Lichvar, and C. V. Noble. ERDC/EL TR-12-1. Vicksburg, MS: U.S. Army Engineer Research and Development Center (Version 2.0), US Army Corps of Engineers, 2012.

1.2.1 Investigations

During the August 5 and 26, 2022 delineation, the Fuss & O'Neill wetland and soil scientist walked transects approximately 50 feet apart within the Subject Parcel in a generally south to north alignment across the width of the subject parcel. Fuss & O'Neill observed vegetation throughout the subject parcel as well as soils, verifying the presence or absence of wetlands.

Subsequent investigations conducted on November 10 and 28, 2022 included further investigation of wetlands delineated in August and additional isolated wetland (non-jurisdictional) identified by Stockman Associates, LLC. During the November 2022 investigations and sites visits, wetland and upland areas were reviewed, soils and vegetation were documented, wetland boundaries were refined, and two new non-jurisdictional isolated wetland was delineated (#6 and #7).

Where Bordering Vegetated Wetlands (BVW) or Isolated Vegetated Wetlands (IVW) was observed, the resource area boundaries were delineated and information regarding vegetation, soils, and hydrology was collected. Each flag location was named based on a numeric-alpha-numeric nomenclature and collected by GPS with sub-meter accuracy. A Professional Land Surveyor located flags on December 13, 2022. The Figures in Attachment A include flag locations located by the Professional Land Surveyor.

Fuss & O'Neill also conducted a desktop review of available online resources prior to performing the wetland delineation including Massachusetts Mapper (MassMapper) and FEMA mapping. The Franklin County FEMA Flood Insurance Rate Map (FIRM, Map No. 250128 0001-0020, effective June 18, 1980) and the Natural Heritage & Endangered Species Program (NHESP) database 15th Edition, effective August 1, 2021 was reviewed for the Subject Parcel.



September 6, 2022 (last revised February 1, 2023) Page 3

1.3 Resource Areas

1.3.1 Resource Areas Not Present

The following resource areas are not located within the Subject Parcel according to MassMapper and the FEMA FIRM:

- FEMA 100-year Floodplain
- Natural Heritage Endangered Species Program (NHESP) Estimated Habitats of Rare Wildlife
- NHESP Priority Habitats of Rare Species
- NHESP Certified Vernal Pools
- Potential Vernal Pools

1.3.2 Resource Areas and Protected Areas Present Within the Site

Bordering Vegetated Wetlands (BVW): Regulatory Framework

Bordering Vegetated Wetlands are defined under 310 CMR 10.55(2)(a) as "freshwater wetlands which border on creeks, rivers, streams, ponds, and lakes. The types of freshwater wetlands are wet meadows, marshes, swamps and bogs. Bordering Vegetated Wetlands are areas where the soils are saturated and/or inundated such that they support a predominance of wetland indicator plants. The ground and surface water regime and the vegetation community which occur in each type of freshwater wetland are specified in M.G.L. c. 131, § 40."

Bordering Vegetated Wetlands are also regulated under the Shutesbury Wetlands Bylaw. Three BVW's were identified during the wetland delineation. BVW's 1 and 3 extend beyond the Subject Parcel and therefore bordering status was not confirmed, but assumed based on mapped DEP wetlands and hydrologic connections. BVW 2 is considered bordering on the pond on 62 Leverett Road via a drop inlet structure. The pond is connected to a mapped wetland system to the east via cross culverts.

BVW: Resource Area Description

BVW 1

Bordering Vegetated Wetland 1 is best described as a seasonally saturated Palustrine Forested Wetland (PFO) and a Palustrine Emergent Wetland (PEM). BVW 1 is located within the northern portion of the Subject Parcel. The western portion of the wetland is primarily forested, while the eastern portion consists of a disturbed, regularly mowed area. Due to recent mowing, species identification was limited, but pockets of sensitive fern (*Onoclea sensibilis*, FACW) were visible. Within the mowed area, the wetland slopes down to the north to a vegetated drainage swale which conveys flow to the west. No standing water was observed within the swale at the time of the delineation. Within the mowed wetland area,




September 6, 2022 (last revised February 1, 2023) Page 4

BVW 1 was generally delineated based on the presence of sensitive fern, observations of multiple soil test holes, and minor changes in topographic relief.

Due to drought conditions reported for the Connecticut River Valley Region since May, hydrologic conditions are not typical for this time of year. According to the Massachsuetts Department of Conservation and Recreation (DCR), the Connecticut River Valley Region experienced the following drought statuses: Level 1 – Mild Drought (May 2022), Level 2 -Significant Drought (June and July 2022), and Level 3 – Critical Drought (August 2022).

Vegetation observed within BVW 1 mowed area includes: sensitive fern, swamp dewberry (Rubus hispidis; FACW), and sedges and grasses. Hydrology indicators include drainage patterns, saturation visible on aerial imagery (World Imagery; updated July 1, 2020), and FAC-neutral test. Soils exhibited a redox dark surface (F6) hydric soil indicator.

The Natural Resource Conservation Service (NRCS) mapped the BVW 1 area as Metacomet fine sandy loam. The mapped soil texture is generally consistent with field observations, but soils observed do not align with the mapped hydric soil rating of 'no'. Detailed information of these soil series mapped within the Site Parcel is included within the NRCS Custom Soil Resource Report in *Attachment E*.



Photographs 1-3 View of BVW 1 test pits from left to right: Test Pit #1, Test Pit #2, Test Pit #3. View of dark yellowish brown colors (yellow arrows) indicative of upland soils directly beneath the Ap horizon.



September 6, 2022 (last revised February 1, 2023) Page 5

BVW 2

BVW 2 is best described as a seasonally saturated PFO wetland located along the eastern border of the Subject Parcel. Vegetation includes: green ash (*Fraxinus pennsylvanica*; FACW), winterberry (*Ilex vertixillata*; FACW), silky dogwood (*Cornus amomum*; FACW), sensitive fern, Oriental bittersweet (*Celastrus orbiculatus*; UPL), and Virginia creeper (*Parthenocissus quinquefolia*; FACU). BVW 2 soils were sandy and exhibited a sandy redox (S5) hydric soil indicator. Soils observed within BVW 2 do not align with the mapped hydric soil rating of 'no'.

Although the only hydrology indicator includes FAC-neutral test, this wetland contained hydrophytic vegetation and hydric soils, and is therefore considered a wetland according to the MassDEP Delineating Bordering Vegetated Wetlands Under the Massachusetts Wetlands Protection Act (March 1995) and Shutesbury Wetland Regulations.

As recommended by Stockman Associates, the western boundary of BVW 2 was revisited during the November 10, 2022 site investigation. One test pit, BVW 2, Test Pit # 4, was dug approximately 13 feet west of the original BVW 2 boundary. The test pit, dug with a spade was advanced to 34 inches at the location below:

• BVW 2, Test Pit #4: 42.450713, -72.415545

Findings from a review of historic aerials and from the soil evaluation of one test pit in BVW 2 are summarized below:

- 1. The earliest aerial photograph available (1938) on Historic Aerials.com shows the land cover as a field within the vicinity of BVW 2. The 1962 historic aerial shows disturbance within the vicinity of BVW 2. In addition, an access route is visible in the 1962 aerial. These areas were altered prior to the "Hatch" Act, Chapter 220, Acts of 195, adopted March 25, 1965 and the MA Wetlands Protection Act of 1972. The soil test pit was advanced within the vicinity of the disturbance visible on the 1962 aerial.
- 2. Within Test Pit #4, a darker horizon was observed between 16 inches and 26 inches. Based on known past disturbance, this horizon is likely a buried A horizon.
- 3. A buried hydric soil (Problem Hydric Soils, Three Chroma Sands NE-S1) was observed within the Test Pit #4 (see yellow arrow in Photograph 7 below). Although the review of the 1962 aerial shows disturbance within the vicinity of the BVW 2 was prior to pertinent regulations, the location of Test Pit #4 was conservatively included in the updated BVW 2 delineation.
- 4. As recommended by Ms. Stockman, the mounded fill pile originally excluded from the BVW 2 delineation is included in the updated BVW 2 delineation. It is assumed the pile was placed after 1965 and in the absence of the pile, a wetland would be present.
- 5. The updated BVW 2 delineation generally follows the toe of access road slope.



September 6, 2022 (last revised February 1, 2023) Page 6



Photographs 1-2 View of BVW 2, Test Pit #4. Buried A horizon indicated by the yellow arrow.

BVW 3

BVW 3 is best described as a seasonally flooded/saturated PEM and PFO. BVW 3 is located south of BVW 1 and extends off the Subject Parcel to the west. BVW 3 is generally located at the toe of slope within a depression. The eastern portion of BVW 3 is a sparsely vegetated convex surface. Vegetation observed within BVW 3 includes: rice cut grass (*Leersia oryzoides*, OBL), American bugleweed (*Lycopus americanus*; OBL), white meadowsweet (*Spiraea alba*; FACW), red maple (*Acer rubrum*, FAC) saplings and trees, unidentified grasses, marsh fern (*Thelypteris palustris*, FACW), and cinnamon fern (*Osmunda cinnamomea*, FACW). Soils exhibited a sandy redox (F5) hydric soil indicator. The NRCS mapped the BVW 3 area as Pilsbury fine sandy loam. Soils observed align with the mapped hydric soil rating of 'yes'. Buried debris was observed between flags 3A-114 and 3A-115. There is potential there could be wetland fill between these flags, but due to the depth of the overburden material (~3 feet), an investigation with hand tools was not possible. Heavy machinery may be required to excavate this area to verify or determine the wetland boundary.

Buffer Zone

Buffer Zone is defined in 310 CMR 10.04 as "that area of land extending 100 feet horizontally outward from the boundary of any area specified in 310 CMR 10.02(1)(a)." Buffer Zone is considered an area subject to protection under the MAWPA, but is not regulated as a resource area under the MAWPA.



September 6, 2022 (last revised February 1, 2023) Page 7

Unlike the MAWPA, the Shutesbury Wetlands Bylaw considers the 100-foot Buffer Zone a separate jurisdictional resource area.

The 100-foot Buffer Zone within the Subject Parcel consists of forested areas and the regularly maintained lawn area within the northern portion of the parcel. The forested areas are vegetated with a combination of deciduous and coniferous trees including red maple, American beech (Fagus grandifolia, FAU), white pine (Pinus strobus; FAU) eastern hemlock (Tsuga canadensis, FACU), and gray birch. Portions of the upland forest consist of a denser understory of mountain laurel and other portions have a more open understory. Additional vegetation observed includes sheep laurel (Kalmia angustifolia; FAC), cinnamon fern, lowbush blueberry (Vaccinium angustifolium; FACU), and eastern teaberry (Gaultheria procumbens; FACU).

Because the wetland delineation did not occur outside of the Subject Parcel, and wetlands were observed adjacent to the Subject Parcel to the west, a No-Contest 100-foot Buffer Zone has been added to along the southwest and southeast boundary of the review area. This No-Contest 100-foot Buffer Zone has been added to maximize protection of potential wetland resource areas off parcel.

1.4 Isolated Vegetated Wetlands (Non-Jurisdictional)

Four IVW's were identified within the Subject Parcel (IVW 4 through 7). These IVW's each included a surface area less than one thousand (1,000) square feet and therefore are not jurisdictional IVWs under the Shutesbury Wetland Regulations. In addition, these IVW's are not subject to jurisdiction or protection under the MAWPA.

Descriptions of these non-jurisdictional IVW's observed within the Subject Parcel review area are provided below for reference.

IVW (Non-Jurisdictional): Description

IVW 4 (663 sf)

IVW 4 is best described as a seasonally saturated/flooded PEM wetland located along the access route to the former radio tower location. IVW 4 is approximately 8 feet wide. This IVW was likely manmade due to compaction from vehicle traffic of upland areas over time. The access road ruts are 0.5 to 1 foot lower elevation than directly adjacent upland areas. IVW 4 likely collects and holds water due to its geomorphic position. No standing water was observed at the time of delineation. Vegetation observed within IVW 4 includes: cranberry (*Vaccinium oxycoccos*; OBL), red maple saplings, white meadowsweet, mountain laurel (*Kalmia latifolia*; FACU), grey birch saplings (*Betula populifolia*), and sedges (*Rhynchospora spp.*). Soils within the tire track areas were compacted. The interior of the road was more densely vegetated and included soils with a sandy redox (S5) hydric soil indicator. Soils observed within IVW 4 do not align with the mapped hydric soil rating of 'no'.



September 6, 2022 (last revised February 1, 2023) Page 8

IVW 5 (167 sf)

IVW 5 is best described as a seasonally saturated/flooded PEM wetland located within the access route just south of IVW 4. IVW 5 is approximately 8 feet wide with an area of 167 sf. This IVW was separated by IVW 4 by an upland island and consists of similar vegetation, hydrology, and disturbance history as IVW 4.

IVW 6 (535 sf)

IVW 6 is best described as a seasonally saturated/flooded PEM wetland located within the access route south of IVW 5. A portion of this IVW extends outside of the access route. The portion within the access route includes deep ruts. Standing water was not observed at the time of the delineation, but this area likely collects and holds water during precipitation events. Hydric soil indicator Depleted Matrix (F3) was observed at the base of the ruts. Vegetation included cranberry (*Vaccinium oxycocus*; OBL), sedges (*Rhynchospora* spp.), and sheep laurel (*Kalmia angustifolia*; FAC).


IVW 7 (321 sf)

IVW 7 is best described as a seasonally saturated/flooded PEM wetland located east of the access route. During the November 28, 2022 delineation, which is outside the growing season, this IVW was holding water. Ponding was not observed in this area during previous site visits. Vegetation observed included cranberries and sheep laurel.



Attachment A

Figures





Subject Parcel 1,000 2,000 Feet

Disclaimer: This map is not the product of a Professional Land Survey. It was created by Fuss & O'Neill, Inc. for general reference, informational, planning and guidance use, and is not a legally authoritative source as to location of natural or manmade features. Proper interpretation of this map may require the assistance of appropriate professional services. Fuss O'Neill, Inc. makes no warrantee, express or implied, related to the spatial accuracy, reliability, completeness, or currentness of this map.


Topographic Map


66 Leverett Road Shutesbury, Massachusetts

February 2023



Figure 1





Wetland Delineation Overview


66 Leverett Road Shutesbury, Massachusetts

February 2023 (last revised)



Figure 2





Wetland Flag Locations


66 Leverett Road Shutesbury, Massachusetts


February 2023 (last revised)



413.452.0445| www.fando.com

Figure 3-1






Wetland Flag Locations

66 Leverett Road Shutesbury, Massachusetts

February 2023 (last revised)



Figure 3-2 Springfield, MA 01103 413.452.0445| www.fando.com





Attachment B Site Photographs





Photo 1: Overview of northern portion of the Subject Parcel, facing BVW 1 (view west, 8/16/22).



Photo 2: View of sensitive fern growing within the mowed portion of BVW 1 near flag 1A-129 (view south, 8/16/22).





Photo 3: View of the forested portion of BVW 1 near flag 1A-112 (view west, 8/5/22).



Photo 4: View of redox concentrations (yellow arrows) visible in BVW 1 soils (8/5/22).





Photo 5: View of BVW 3 near flag 3B-110 (view north, 8/16/22)



Photo 6: View of the sandy redox hydric soil in BVW 3.





Photo 7: View of BVW 2 (view southeast, 8/5/22).



Photo 8: View of IVW 4 within the access route near flag 4A-102 (view south, 8/16/22).






Photo 9: View of IVW 5 (11/28/22).



Photo 10: View of IVW 6 (view northeast, 11/10/22).





Photo 11: View of IVW 7 (view east, 11/28/22).




Photo 12: Representative view of the access route to the former radio tower location (view south, 8/5/22).





Photo 13: View of the former radio tower location (view west, 8/5/22).



Photo 14: Representative view of upland forest within 100 feet of the former radio tower location (view west, 8/16/22).



Attachment C Wetland Determination Data Forms

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: 66 Leverett Road	City/County: Shu	utesbury	Sampling Date: 8/5/2022
Applicant/Owner: Town of Shutesbury	<u> </u>	State:	MA Sampling Point: 1A-129
Investigator(s): April Doroski, PWS, CPSS, Fuss & O'Neill	Section, Townshi	ip, Range:	<u> </u>
Landform (hillside, terrace, etc.): hillside		ve, convex, none): none	Slope (%): 3-8
Subregion (LRR or MLRA): LRR R, MLRA 144A Lat: 42.4		Long: -72.416368	Datum: NAD83
Soil Map Unit Name: 368B - Metacomet fine sandy loam and			fication: PEM
Are climatic / hydrologic conditions on the site typical for this			·
, ,		No X (If no, explain	
Are Vegetation X , Soil X , or Hydrology X	. •	re "Normal Circumstances" pr	
Are Vegetation X, Soil X, or Hydrology X	•	f needed, explain any answers	·
SUMMARY OF FINDINGS – Attach site map s	nowing sampling poli	nt locations, transects,	, important features, etc.
Hydrophytic Vegetation Present? Yes X N	lo Is the Samp	led Area	
l ,	lo within a We	tland? Yes X	No
Wetland Hydrology Present? Yes X N	lf yes, option	nal Wetland Site ID: BVW 1A	
Due to drought conditions reported for the Connecticut Rive According to the Massachsuetts Department of Conservation conditions starting in May 2022 and continuing through Aug	ion and Recreation (DCR) the		
HYDROLOGY			
Wetland Hydrology Indicators:		Secondary India	cators (minimum of two required)
Primary Indicators (minimum of one is required; check all the			oil Cracks (B6)
	ter-Stained Leaves (B9)	X Drainage P	
	atic Fauna (B13)		Lines (B16)
l ——	l Deposits (B15)		n Water Table (C2)
	rogen Sulfide Odor (C1)		urrows (C8)
	dized Rhizospheres on Living sence of Reduced Iron (C4)		Visible on Aerial Imagery (C9) Stressed Plants (D1)
l ——	ent Iron Reduction in Tilled S		ic Position (D2)
	n Muck Surface (C7)	· · · —	quitard (D3)
	er (Explain in Remarks)		raphic Relief (D4)
Sparsely Vegetated Concave Surface (B8)	У (Елемин сель	X FAC-Neutr	
Field Observations:			
	epth (inches):		
	epth (inches):		
	epth (inches):	Wetland Hydrology Presen	t? Yes X No
(includes capillary fringe)	<u> </u>		
Describe Recorded Data (stream gauge, monitoring well, a	ierial photos, previous inspec	ctions), if available:	
Remarks: The plot was taken within the disturbed (mowed) portion of observed within the forested portion includes water stained	· ·	getated swale. Portions of the	wetland are forested. Hydrology

VEGETATION – Use scientific names of plants. Sampling Point: 1A-129 Absolute Dominant Indicator Tree Stratum (Plot size: % Cover **Dominance Test worksheet:** Species? Status 1. **Number of Dominant Species** 2. That Are OBL, FACW, or FAC: (A) 3. **Total Number of Dominant** 4. Species Across All Strata: 2 (B) 5. Percent of Dominant Species That Are OBL, FACW, or FAC: 50.0% (A/B) Prevalence Index worksheet: =Total Cover Total % Cover of: Sapling/Shrub Stratum (Plot size: 15 OBL species x 1 = **FACW** species x 2 = 1. 2. 0 x 3 = FAC species 0 x 4 = 3. FACU species 0 4. UPL species x 5 = 5. Column Totals: 25 (A) 50 Prevalence Index = B/A = 2.00 **Hydrophytic Vegetation Indicators:** =Total Cover 1 - Rapid Test for Hydrophytic Vegetation Herb Stratum (Plot size: 5) 2 - Dominance Test is >50% Onoclea sensibilis 20 Yes **FACW** X 3 - Prevalence Index is ≤3.0¹ Rubus hispidus 5 **FACW** 4 - Morphological Adaptations¹ (Provide supporting data in Remarks or on a separate sheet) 5 3. No Sedges spp. 4. 60 X Problematic Hydrophytic Vegetation¹ (Explain) Grass spp. 5. ¹Indicators of hydric soil and wetland hydrology must 6. be present, unless disturbed or problematic. 7. **Definitions of Vegetation Strata:** 8. Tree - Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height. Sapling/shrub - Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall. Herb - All herbaceous (non-woody) plants, regardless 90 =Total Cover of size, and woody plants less than 3.28 ft tall. Woody Vine Stratum (Plot size: 5) Woody vines - All woody vines greater than 3.28 ft in 1. height. 2. Hydrophytic 3. Vegetation Yes X No Present? =Total Cover Remarks: (Include photo numbers here or on a separate sheet.) Area of wetland plot is problematic due to regular mowing. Identification of grass species is not possible. Sensitive fern observed in pockets. Vegetation observed within the forested portion of the wetland consisted of cinnamon fern, sensitive fern, grey birch, winterberry, and red maple.

SOIL Sampling Point: 1A-129

Profile Description: (Describe to the depth needed to document the indicator or confirm the absence of indicators.) Depth Matrix Redox Features								
Depth	Matrix				-	. 2	- .	
(inches)	Color (moist)	<u>%</u>	Color (moist)	<u>%</u>	Type'	Loc ²	Texture	Remarks
0-7	10YR 2/2	90	7.5YR 4/6	10	<u>C</u>	<u>M</u>	Loamy/Clayey	Prominent redox concentrations
7-10	10YR 4/3	93	10YR 3/6	7	С	M	Loamy/Clayey	Distinct redox concentrations
10-16	2.5Y 5/3	90	10YR 4/6	10	<u>C</u>	M	Loamy/Clayey	Prominent redox concentrations
¹ Type: C=	Concentration, D=Dep	letion, RI	M=Reduced Matrix, C	S=Cover	ed or Coa	ated Sand	d Grains. ² Lo	cation: PL=Pore Lining, M=Matrix.
	oil Indicators:							or Problematic Hydric Soils ³ :
_	sol (A1)		Polyvalue Below	Surface	(S8) (LR	R R,		ck (A10) (LRR K, L, MLRA 149B)
	Epipedon (A2)		MLRA 149B)		() (•		rairie Redox (A16) (LRR K, L, R)
	Histic (A3)		Thin Dark Surfac	ا) (20) م	DD D M	I DA 1/0		cky Peat or Peat (S3) (LRR K, L, R)
	` '							
	ogen Sulfide (A4)		High Chroma Sa					e Below Surface (S8) (LRR K, L)
	fied Layers (A5)		Loamy Mucky M			(, L)		k Surface (S9) (LRR K, L)
Deple	ted Below Dark Surfac	e (A11)	Loamy Gleyed M	latrix (F2	2)		Iron-Mar	nganese Masses (F12) (LRR K, L, R)
Thick	Dark Surface (A12)		Depleted Matrix	(F3)			Piedmor	nt Floodplain Soils (F19) (MLRA 149B)
	y Mucky Mineral (S1)		X Redox Dark Surf					podic (TA6) (MLRA 144A, 145, 149B)
	y Gleyed Matrix (S4)		Depleted Dark S					ent Material (F21)
					1)			
	y Redox (S5)		Redox Depression	, ,				allow Dark Surface (TF12)
Stripp	ed Matrix (S6)		Marl (F10) (LRR	K , L)			Other (E	xplain in Remarks)
Dark	Surface (S7)							
³ Indicators	of hydrophytic vegeta	tion and v	vetland hydrology mu	st be pre	sent, unle	ess distur	bed or problematic	
Restrictiv	e Layer (if observed):	:						
Type: N	IA .							
Depth (i	nches):						Hydric Soil Pre	esent? Yes <u>X</u> No
Remarks:								
								CS Field Indicators of Hydric Soils
version 7.0	0 March 2013 Errata. (I	http://www	v.nrcs.usda.gov/Interr	net/FSE_	DOCUME	ENTS/nrc	s142p2_051293.dd	ocx).
Soil was n	noistened prior to color	ing.						

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Applicant/Owner: Town of Shutesbury April Doroski, PWS, CPSS, Fuss & O'Neill Section, Township, Range: Local relief (concave, convex, none): none Slope (%): 3-8 Subregion (LRR or MLRA): LRR R, MLRA 144A Lat: 42.450612 Long: -72.415453 Datum: NAD83 Soil Map Unit Name: 368B - Metacomet fine sandy loam, 3 to 8 percent slopes Are climatic / hydrologic conditions on the site typical for this time of year? Are Vegetation X , Soil X , or Hydrology significantly disturbed? Are "Normal Circumstances" present? Yes No X Are Vegetation , Soil X , or Hydrology X naturally problematic? (If needed, explain any answers in Remarks.) SUMMARY OF FINDINGS - Attach site map showing sampling point locations, transects, important features, etc. Hydrophytic Vegetation Present? Yes X No Is the Sampled Area within a Wetland? Yes X No Within a Wetland? Yes X No Is the Sampled Area within a Wetland?	Project/Site: 66 Leverett Road	City/County: Shutesbury Sampling Date: 8/5/2022, 11/10/2022			
April Doroski, PWS, CPSS, Fuss & O'Neill Section, Township, Range:	-				
Local relief (concave, convex, none): none					
Solf Map Unit Name: 3688 - Metacomet fine sandy loam, 3 to 8 percent slopes					
Soil Map Unit Name: 368B - Metacomet fine sandy loam, 3 to 8 percent slopes	· · · · · · · · · · · · · · · · · · ·				
Are climatic / hydrologic conditions on the site typical for this time of year? Yes No X (If no, explain in Remarks.) Are Vegetation X, Soil X, or Hydrology significantly disturbed? Are "Normal Circumstances" present? Yes No X have Vegetation S. Soil X, or Hydrology X naturally problematic? (If needed, explain any answers in Remarks.) SUMMARY OF FINDINGS — Attach site map showing sampling point locations, transects, important features, etc. Hydrophytic Vegetation Present? Yes X No Is the Sampled Area within a Wettand? Yes X No Wetland Hydrology Present? Yes No If yes, optional Wetland Site ID: BVW 2 Wetland Hydrology Present? Yes No If yes, optional Wetland Site ID: BVW 2 Wetland Hydrology Present? Yes No If yes, optional Wetland Site ID: BVW 2 Wetland Hydrology Present? Yes No If yes, optional Wetland Site ID: BVW 2 Wetland Hydrology Indicators (minimum of nonecificut River Valley Region since May, hydrologic conditions are not typical for this time of year. According to the Massachsuetts Department of Conservation and Recreation (DCR) the Connecticut River Valley Region experienced drought conditions reported for the Connecticut River Valley Region experienced drought conditions starting in May 2022 and continuing through August 2022. **PIMORIAN MARIAN M	· · · · · · · · · · · · · · · · · · ·				
Are Vegetation X , Soil X , or Hydrology significantly disturbed? Are "Normal Circumstances" present? Yes No X re Vegetation , Soil X , or Hydrology X naturally problematic? (If needed, explain any answers in Remarks.) SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc. Hydrophytic Vegetation Present? Yes X No Is the Sampled Area within a Wetland? Yes X No If yes, optional Wetland Bite ID: BVW 2 Remarks: (Explain alternative procedures here or in a separate report.) Due to drought conditions reported for the Connecticut River Valley Region since May, hydrologic conditions are not typical for this time of year. According to the Massachsustes Department of Conservation and Recreation (DCR) the Connecticut River Valley Region experienced drought conditions starting in May 2022 and continuing through August 2022. HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is required; check all that apply) Surface Water (A1) Water-Stained Leaves (B9) Jufface Soil Cracks (B6) Surface Water (A1) Water-Stained Leaves (B9) Jufface Soil Cracks (B6) Surface Water (A1) Aquatic Fauna (B13) Water Marks (B1) Hydrogen Sulfide Odor (C1) Sediment Deposits (B1) Presence of Reduced Iron (C4) Sediment Deposits (B3) Presence of Reduced Iron (C4) Surface Water (A1) Appla Mat or Crust (B4) Recent Iron Reduction in Tilled Soils (C6) Geomorphic Position (D2) Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Juricotopographic Relief (D4) Sparsely Vegetated Concave Surface (B8) Presence of Reduced Iron (C4) Sparsely Vegetated Concave Surface (B8) Field Observations: Water Table Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Water Table Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Soil Map Unit Name: <u>368B - Metacomet fine sandy loam, 3 to 8 pe</u>	NWI classification: PFO			
Summary OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc. Hydrophytic Vegetation Present? Yes X No Is the Sampled Area within a Wetland? Yes X No If yes, optional Wetland Site ID: BVW 2 Wetland Hydrology Present? Yes X No If yes, optional Wetland Site ID: BVW 2 Wetland Hydrology Present? Yes X No Yes X Yes X X No Yes X Yes X Xo Yes Xo Xo X Yes X Xo Yes Xo Xo X Xo Yes Xo Xo Xo Xo Xo Yes Xo	Are climatic / hydrologic conditions on the site typical for this time of	of year? Yes No X (If no, explain in Remarks.)			
SUMMARY OF FINDINGS – Attach site map showing sampling point locations, transects, important features, etc. Hydrophytic Vegetation Present? Yes X No Within a Wetland? Yes X No Wetland Hydrology Present? Yes No Wetland Hydrology Indicators reported for the Connecticut River Valley Region since May, hydrologic conditions are not typical for this time of year. According to the Massachsuetts Department of Conservation and Recreation (DCR) the Connecticut River Valley Region experienced drought conditions starting in May 2022 and continuing through August 2022. HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is required; check all that apply) Surface Soil Cracks (B6) Surface Water (A1) Water-Stained Leaves (B9) Drainage Patterns (B10) High Water Table (A2) Aquatic Fauna (B13) Moss Trim Lines (B16) Saturation (A3) Marl Deposits (B15) Dry-Season Water Table (C2) Water Marks (B1) Hydrogen Sulfide Oddr (C1) Crayfish Burrows (C8) Sediment Deposits (B2) Oxidized Rhizospheres on Living Roots (C3) Saturation Visible on Aerial Imagery (C9) Drift Deposits (B3) Presence of Reduced Iron (C4) Stunted or Stressed Plants (D1) Algal Mat or Crust (B4) Recent Iron Reduction in Tilled Soils (C6) Geomorphic Position (D2) Iron Deposits (B5) Thin Muck Surface (C7) Shallow Aquitard (D3) Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Microtopographic Relief (D4) Sparsely Vegetated Concave Surface (B8) Thin Muck Surface (C7) Shallow Aquitard (D3) Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Microtopographic Relief (D4) Sparsely Vegetated Concave Surface (B8) Film (No. Sparsely Vegetated Con	Are Vegetation X, Soil X, or Hydrology signific	cantly disturbed? Are "Normal Circumstances" present? Yes No _X			
Hydrophytic Vegetation Present? Yes X No If the Sampled Area within a Wetland? Yes X No If yes, optional Wetland Site ID: BVW 2 Wetland Hydrology Present? Yes No If yes, optional Wetland Site ID: BVW 2	Are Vegetation, SoilX_, or HydrologyX_ natural	lly problematic? (If needed, explain any answers in Remarks.)			
Hydric Soil Present? Wetland Hydrology Present? Yes No No If yes, optional Wetland? If yes, optional Wetland Site ID: BVW 2 Remarks: (Explain alternative procedures here or in a separate report.) Due to drought conditions reported for the Connecticut River Valley Region since May, hydrologic conditions are not typical for this time of year. According to the Massachsuetts Department of Conservation and Recreation (DCR) the Connecticut River Valley Region experienced drought conditions starting in May 2022 and continuing through August 2022. HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is required; check all that apply) Surface Water (A1) High Water Table (A2) Aquatic Fauna (B13) Saturation (A3) Moss Trim Lines (B16) Saturation (A3) Water Marks (B1) Hydrogen Sulfide Odor (C1) Sediment Deposits (B2) Oxidized Rhizospheres on Living Roots (C3) Saturation Visible on Aerial Imagery (C9) Drift Deposits (B3) Presence of Reduced Iron (C4) Algal Mat or Crust (B4) Recent Iron Reduction in Tilled Soils (C6) Iron Deposits (B5) Iron Deposits (B5) Iron Deposits (B5) Iron Deposits (B5) Iron Deposits (B6) Field Observations: Surface Water Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Saturation	SUMMARY OF FINDINGS – Attach site map showing	ng sampling point locations, transects, important features, etc.			
Hydric Soil Present? Wetland Hydrology Present? Yes No No If yes, optional Wetland? If yes, optional Wetland Site ID: BVW 2 Remarks: (Explain alternative procedures here or in a separate report.) Due to drought conditions reported for the Connecticut River Valley Region since May, hydrologic conditions are not typical for this time of year. According to the Massachsuetts Department of Conservation and Recreation (DCR) the Connecticut River Valley Region experienced drought conditions starting in May 2022 and continuing through August 2022. HYDROLOGY Wetland Hydrology Indicators: Primary Indicators (minimum of one is required; check all that apply) Surface Water (A1) High Water Table (A2) Aquatic Fauna (B13) Saturation (A3) Moss Trim Lines (B16) Saturation (A3) Water Marks (B1) Hydrogen Sulfide Odor (C1) Sediment Deposits (B2) Oxidized Rhizospheres on Living Roots (C3) Saturation Visible on Aerial Imagery (C9) Drift Deposits (B3) Presence of Reduced Iron (C4) Algal Mat or Crust (B4) Recent Iron Reduction in Tilled Soils (C6) Iron Deposits (B5) Iron Deposits (B5) Iron Deposits (B5) Iron Deposits (B5) Iron Deposits (B6) Field Observations: Surface Water Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Saturation	Hydrophytic Vegetation Present? Yes X No	Is the Sampled Area			
Remarks: (Explain alternative procedures here or in a separate report.) Due to drought conditions reported for the Connecticut River Valley Region since May, hydrologic conditions are not typical for this time of year. According to the Massachsulets Department of Conservation and Recreation (DCR) the Connecticut River Valley Region experienced drought conditions starting in May 2022 and continuing through August 2022. Hydrology Wetland Hydrology Indicators:		within a Wetland? Yes X No			
Due to drought conditions reported for the Conservation and Recreation (DCR) the Connecticut River Valley Region experienced drought conditions starting in May 2022 and continuing through August 2022. HYDROLOGY	Wetland Hydrology Present? Yes No	If yes, optional Wetland Site ID: BVW 2			
Wetland Hydrology Indicators: Secondary Indicators (minimum of two required) Primary Indicators (minimum of one is required; check all that apply) Surface Water (A1) Water-Stained Leaves (B9) Drainage Patterns (B10) High Water Table (A2) Aquatic Fauna (B13) Moss Trim Lines (B16) Saturation (A3) Hydrogen Sulfide Odor (C1) Crayfish Burrows (C8) Sediment Deposits (B2) Oxidized Rhizospheres on Living Roots (C3) Saturation Visible on Aerial Imagery (C9) Drift Deposits (B3) Presence of Reduced Iron (C4) Stunted or Stressed Plants (D1) Algal Mat or Crust (B4) Recent Iron Reduction in Tilled Soils (C6) Geomorphic Position (D2) Inon Deposits (B5) Thin Muck Surface (C7) Shallow Aquitard (D3) Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Microtopographic Relief (D4) Sparsely Vegetated Concave Surface (B8) Ves No Depth (inches): Water Table Present? Yes No Depth (inches): Water Table Present? Yes No Wetland Hydrology Present? Yes No Saturation Present? Yes No Depth (inches): Wetland Hydrology Present? Yes No	conditions starting in May 2022 and continuing through August 20				
Primary Indicators (minimum of one is required; check all that apply) Surface Soil Cracks (B6) Surface Water (A1) High Water Table (A2) Aquatic Fauna (B13) Moss Trim Lines (B16) Saturation (A3) Marl Deposits (B15) Dry-Season Water Table (C2) Crayfish Burrows (C8) Sediment Deposits (B2) Drift Deposits (B3) Presence of Reduced Iron (C4) Algal Mat or Crust (B4) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Soil Cracks (B6) Drainage Patterns (B10) Moss Trim Lines (B16) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Stunted or Stressed Plants (D1) Stunted or Stressed Plants (D1) Geomorphic Position (D2) Inon Deposits (B5) Thin Muck Surface (C7) Shallow Aquitard (D3) Microtopographic Relief (D4) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:					
Surface Water (A1)					
High Water Table (A2) Saturation (A3) Marl Deposits (B15) Dry-Season Water Table (C2) Water Marks (B1) Hydrogen Sulfide Odor (C1) Sediment Deposits (B2) Oxidized Rhizospheres on Living Roots (C3) Drift Deposits (B3) Presence of Reduced Iron (C4) Algal Mat or Crust (B4) Iron Deposits (B5) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Water Table Present? Yes No X Depth (inches): Saturation Visible on Aerial Photos, previous inspections), if available: Wetland Hydrology Present? Yes No Cincludes capillary fringe) Moss Trim Lines (B16) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Saturation Present? Yes No X Depth (inches): Wetland Hydrology Present? Yes No Cincludes capillary fringe)					
Saturation (A3) Water Marks (B1) Water Marks (B1) Sediment Deposits (B2) Drift Deposits (B3) Presence of Reduced Iron (C4) Algal Mat or Crust (B4) In Muck Surface (C7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Water Table Present? Yes No X Depth (inches): Saturation (A3) Marl Deposits (B15) Dry-Season Water Table (C2) Crayfish Burrows (C8) Saturation Visible on Aerial Imagery (C9) Stunted or Stressed Plants (D1) Geomorphic Position (D2) Shallow Aquitard (D3) Microtopographic Relief (D4) FAC-Neutral Test (D5) Field Observations: Surface Water Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Saturation Present? Yes No Metland Hydrology Present? Yes No No No No No No No No No N					
Water Marks (B1)	 :				
Sediment Deposits (B2) Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Water Table Present? Yes No X Depth (inches): Saturation Visible on Aerial Imagery (C9) Stunted or Stressed Plants (D1) Geomorphic Position (D2) Shallow Aquitard (D3) Microtopographic Relief (D4) X FAC-Neutral Test (D5) Field Observations: Surface Water Present? Yes No X Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:					
Drift Deposits (B3) Algal Mat or Crust (B4) Iron Deposits (B5) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Yes No X Depth (inches): Saturation Present? Yes No X Depth (inches): Saturation Present? Yes No X Depth (inches): Secribe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:					
Algal Mat or Crust (B4)					
Iron Deposits (B5) Inundation Visible on Aerial Imagery (B7) Sparsely Vegetated Concave Surface (B8) Field Observations: Surface Water Present? Water Table Present? Yes No X Depth (inches): Saturation Present? Yes No X Depth (inches): Sequential Muck Surface (C7) Microtopographic Relief (D4) X FAC-Neutral Test (D5) Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:					
Inundation Visible on Aerial Imagery (B7) Other (Explain in Remarks) Microtopographic Relief (D4) Sparsely Vegetated Concave Surface (B8) X FAC-Neutral Test (D5) Field Observations: Surface Water Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Saturation Present? Yes No X Depth (inches): Wetland Hydrology Present? Yes No Concludes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:					
Sparsely Vegetated Concave Surface (B8) X FAC-Neutral Test (D5) Field Observations: Surface Water Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Saturation Present? Yes No X Depth (inches): Wetland Hydrology Present? Yes No Concludes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:		• • • • • • • • • • • • • • • • • • • •			
Surface Water Present? Yes No X Depth (inches): Water Table Present? Yes No X Depth (inches): Saturation Present? Yes No X Depth (inches): (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	· · · · · · · · · ·				
Water Table Present? Yes No X Depth (inches): Saturation Present? Yes No X Depth (inches): (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Field Observations:				
Saturation Present? Yes No X Depth (inches): Wetland Hydrology Present? Yes No (includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Surface Water Present? Yes NoX Depth (inc	ches):			
(includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:	Water Table Present? Yes No X Depth (inc	ches):			
Describe Recorded Data (stream gauge, monitoring well, aerial photos, previous inspections), if available:		ches): Wetland Hydrology Present? Yes No			
Remarks:	Describe Recorded Data (stream gauge, monitoring well, aerial pl	hotos, previous inspections), if available:			
Remarks:					
	Remarks:				
	Nonano.				

VEGETATION – Use scientific names of plants. Sampling Point: 2A-101 Absolute Dominant Indicator **Dominance Test worksheet:** Tree Stratum (Plot size: % Cover Species? Status 1. Fraxinus pennsylvanica 80 Yes **FACW Number of Dominant Species** 2. That Are OBL, FACW, or FAC: (A) 3. **Total Number of Dominant** 4. Species Across All Strata: 6 (B) 5. Percent of Dominant Species That Are OBL, FACW, or FAC: 6. 66.7% (A/B) Prevalence Index worksheet: 7. 80 =Total Cover Total % Cover of: Sapling/Shrub Stratum (Plot size: 15 OBL species 0 x 1 =llex verticillata **FACW FACW** species x 2 = 1. 5 Yes **FACW** 0 x 3 = 2. Cornus amomum FAC species 0 5 3. FACU species x 4 = 5 4. UPL species x 5 = 25 5. Column Totals: 186 (A) 397 (B) 6. Prevalence Index = B/A = 2.13 7. **Hydrophytic Vegetation Indicators:** 15 =Total Cover X 1 - Rapid Test for Hydrophytic Vegetation Herb Stratum (Plot size: 5) X 2 - Dominance Test is >50% Onoclea sensibilis 80 1. **FACW** X 3 - Prevalence Index is ≤3.0¹ Fraxinus pennsylvanica **FACW** 4 - Morphological Adaptations¹ (Provide supporting data in Remarks or on a separate sheet) 3. 4. Problematic Hydrophytic Vegetation¹ (Explain) 5. ¹Indicators of hydric soil and wetland hydrology must 6. be present, unless disturbed or problematic. 7. **Definitions of Vegetation Strata:** 8. Tree - Woody plants 3 in. (7.6 cm) or more in diameter 9. at breast height (DBH), regardless of height. Sapling/shrub - Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall. 11. Herb - All herbaceous (non-woody) plants, regardless 81 =Total Cover of size, and woody plants less than 3.28 ft tall. Woody Vine Stratum (Plot size: 5) Woody vines - All woody vines greater than 3.28 ft in UPL height. 1. Celastrus orbiculatus 2. Parthenocissus quinquefolia Yes **FACU** Hydrophytic 3. Vegetation 4. Present? Yes X No 10 =Total Cover Remarks: (Include photo numbers here or on a separate sheet.)

SOIL Sampling Point: 2A-101

	escription: (Describe	to the de				or or conf	firm the absence	of indicators.)
Depth	Matrix	0/		x Featur	4	1 - 2	T 4	Demode
(inches)	Color (moist)	<u>%</u>	Color (moist)	<u>%</u>	Type'	Loc ²	Texture	Remarks
0-5	10YR 2/1	100					Sandy	
5-12	10YR 3/2	98	10YR 3/4	2	<u>C</u>	<u>M</u>	Sandy	Distinct redox concentrations
								
			_					
¹ Type: C=	=Concentration, D=Dep	oletion, RN	/I=Reduced Matrix, C	S=Cove	red or Coa	ated Sand	l Grains. ² Lo	cation: PL=Pore Lining, M=Matrix.
-	oil Indicators:							or Problematic Hydric Soils ³ :
	sol (A1)		Polyvalue Below	/ Surface	e (S8) (LR	R R,		ick (A10) (LRR K, L, MLRA 149B)
	: Epipedon (A2) : Histic (A3)		MLRA 149B) Thin Dark Surfa	00 (50) (IDDD M	II DA 140		rairie Redox (A16) (LRR K, L, R)
	ogen Sulfide (A4)	•	High Chroma Sa					icky Peat or Peat (S3) (LRR K, L, R) ie Below Surface (S8) (LRR K, L)
	fied Layers (A5)	•	Loamy Mucky M					rk Surface (S9) (LRR K, L)
	eted Below Dark Surfac	e (A11)	Loamy Gleyed N			L , L)		nganese Masses (F12) (LRR K, L, R)
	Dark Surface (A12)	, (, (, , , ,	Depleted Matrix		-,			nt Floodplain Soils (F19) (MLRA 149B)
	y Mucky Mineral (S1)		Redox Dark Sur)			podic (TA6) (MLRA 144A, 145, 149B)
	y Gleyed Matrix (S4)	•	Depleted Dark S					ent Material (F21)
	y Redox (S5)	•	Redox Depressi	ons (F8)				allow Dark Surface (TF12)
Stripp	ped Matrix (S6)		Marl (F10) (LRR	(K, L)			Other (E	xplain in Remarks)
Dark	Surface (S7)							
31 11 1								
	s of hydrophytic vegeta		vetland hydrology mu	st be pre	esent, unic	ess disturi	ped or problemation	
Type: N	ve Layer (if observed) NA	•						
Depth (i							Hydric Soil Pr	esent? Yes X No
Remarks:							, , , , , , , , , , , , , , , , , , ,	
		orthcentra	I and Northeast Regi	onal Sup	plement \	ersion 2.0	0 to reflect the NR	CS Field Indicators of Hydric Soils
	0 March 2013 Errata. (http://wwv	v.nrcs.usda.gov/Inter	net/FSE_	_DOCUM	ENTS/nrc	s142p2_051293.d	ocx).
Soil was n	moistened for coloring.							

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: 66 Leverett Road	City/County: Shutesbury		Sampling Date:	8/5/2022
Applicant/Owner: Town of Shutesbury		State:		Point: 3B-110
Investigator(s): April Doroski, PWS, CPSS, Fuss & O'Nei	Il Section, Township, Range:			
Landform (hillside, terrace, etc.): depression	Local relief (concave, convex, r	none): convex	Slor	pe (%): 3-8
Subregion (LRR or MLRA): LRR R, MLRA 144A Lat: 42.		2.416383		n: NAD83
			-	I. IVADOO
Soil Map Unit Name: 75B - Pillsbury fine sandy loam			fication: PEM	
Are climatic / hydrologic conditions on the site typical for the		X (If no, explair		
Are Vegetation X, Soil X, or Hydrology		Circumstances" pr		No X
Are Vegetation, Soil, or HydrologyX	_ naturally problematic? (If needed, ex	xplain any answer	s in Remarks.)	
SUMMARY OF FINDINGS – Attach site map	showing sampling point locatio	ns, transects	, important feat	ures, etc.
Hydrophytic Vegetation Present? Yes X	No Is the Sampled Area			
	No within a Wetland?	Yes X	No	
	No If yes, optional Wetland			
Remarks: (Explain alternative procedures here or in a se				
Due to drought conditions reported for the Connecticut Ri	ver Valley Region since May, hydrologic o			
According to the Massachsuetts Department of Conserva		ut River Valley Re	gion experienced dr	ought
conditions starting in May 2022 and continuing through A	ugust 2022.			
HYDROLOGY				
Wetland Hydrology Indicators:		-	cators (minimum of	two required)
Primary Indicators (minimum of one is required; check all	····		oil Cracks (B6)	
	ater-Stained Leaves (B9)			
	uatic Fauna (B13) rrl Deposits (B15)		n Water Table (C2)	
	drogen Sulfide Odor (C1)		urrows (C8)	
 -	idized Rhizospheres on Living Roots (C3)		Visible on Aerial Ima	agery (C9)
	esence of Reduced Iron (C4)		Stressed Plants (D1	
	cent Iron Reduction in Tilled Soils (C6)		ic Position (D2)	,
	in Muck Surface (C7)		quitard (D3)	
Inundation Visible on Aerial Imagery (B7) Oth	ner (Explain in Remarks)	Microtopog	graphic Relief (D4)	
X Sparsely Vegetated Concave Surface (B8)		X FAC-Neutr	al Test (D5)	
Field Observations:				
	Pepth (inches):			
	Depth (inches):			
	Pepth (inches): Wetland H	ydrology Presen	t? Yes X	No
(includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well,		ailahla.		
Describe Recorded Data (stream gauge, monitoring well,	aeriai priotos, previous irispections), ii ava	allable.		
Remarks:				
The plot was taken within a sparsely vegetated area whic	h could be a potential vernal pool. No egg	masses were obs	served at the time of	delineation.
Portions of this BVW are forested.				

VEGETATION – Use scientific names of plants. Sampling Point: 3B-110 Absolute Dominant Indicator Tree Stratum (Plot size: % Cover **Dominance Test worksheet:** Species? Status 1. **Number of Dominant Species** 2. That Are OBL, FACW, or FAC: (A) 3. **Total Number of Dominant** 4. Species Across All Strata: 3 (B) 5. Percent of Dominant Species That Are OBL, FACW, or FAC: 33.3% (A/B) Prevalence Index worksheet: =Total Cover Total % Cover of: Sapling/Shrub Stratum (Plot size: 15) OBL species 25 x 1 = **FACW** species 5 x 2 = 1. 2. FAC species x 3 = 0 x 4 = 3. FACU species 0 4. UPL species x 5 = Column Totals: 5. 32 (A) 41 (B) 6. Prevalence Index = B/A = 1.28 **Hydrophytic Vegetation Indicators:** 5 =Total Cover X 1 - Rapid Test for Hydrophytic Vegetation Herb Stratum (Plot size: 5) 2 - Dominance Test is >50% Leersia oryzoides 20 Yes X 3 - Prevalence Index is ≤3.0¹ OBL 20 Yes 4 - Morphological Adaptations¹ (Provide supporting Grass spp. data in Remarks or on a separate sheet) 5 3. No OBL Lycopus americanus 4. Spiraea alba 5 **FACW** Problematic Hydrophytic Vegetation¹ (Explain) 5. Acer rubrum No FAC ¹Indicators of hydric soil and wetland hydrology must 6. be present, unless disturbed or problematic. 7. **Definitions of Vegetation Strata:** 8. Tree - Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height. Sapling/shrub - Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall. 11. Herb - All herbaceous (non-woody) plants, regardless 52 =Total Cover of size, and woody plants less than 3.28 ft tall. Woody Vine Stratum (Plot size: 5) Woody vines - All woody vines greater than 3.28 ft in 1. height. 2. Hydrophytic 3. Vegetation Yes X No____ Present? =Total Cover Remarks: (Include photo numbers here or on a separate sheet.) Additional vegetation observed outsite of the plot includes marsh fern, sedges, red maple, and cinnamon fern.

SOIL Sampling Point: 3B-110

Drofile Do	scription: (Describe	to the de	onth pooded to decu	mont th	o indicate	r or oon	firm the cheenes	of indicators \	
Depth	Matrix	to the de		Feature		or Com	iiiiii tile abselice	of indicators.)	
•	Color (moist)	%	Color (moist)	%		Loc ²	Texture	Remarks	
(inches)					Type ¹				4:
0-4	2.5Y 4/2	99	10YR 5/8		<u>C</u>	<u>M</u>	Sandy	Prominent redox concentra	
4-10	5Y 5/2	97	2.5Y 5/6	3	<u>C</u>	M	Sandy	Prominent redox concentra	ations
¹ Type: C=	Concentration, D=Dep	letion, RI	M=Reduced Matrix, C	S=Cover	ed or Coa	ated Sand	Grains. ² Lo	cation: PL=Pore Lining, M=Mat	trix.
Hydric So	il Indicators:							or Problematic Hydric Soils ³ :	
Histos	sol (A1)		Polyvalue Below	Surface	(S8) (LR	R R,	2 cm Mu	ck (A10) (LRR K, L, MLRA 149	B)
	Epipedon (A2)		MLRA 149B)					rairie Redox (A16) (LRR K, L, R	
	Histic (A3)		Thin Dark Surfac					cky Peat or Peat (S3) (LRR K , I	
	gen Sulfide (A4)		High Chroma Sa	-				e Below Surface (S8) (LRR K, L	L)
	ied Layers (A5)	- (044)	Loamy Mucky Mi	-		(, L)		k Surface (S9) (LRR K, L)	. D)
	ted Below Dark Surface	e (A11)	Loamy Gleyed M		2)			nganese Masses (F12) (LRR K ,	-
	Dark Surface (A12) Mucky Mineral (S1)		Depleted Matrix Redox Dark Surf	. ,				nt Floodplain Soils (F19) (MLRA podic (TA6) (MLRA 144A, 145 ,	-
	Gleyed Matrix (S4)		Depleted Dark S					ent Material (F21)	1430)
	Redox (S5)		Redox Depression	•	,			allow Dark Surface (TF12)	
	ed Matrix (S6)		Marl (F10) (LRR	. ,				xplain in Remarks)	
	Surface (S7)			, ,				,	
	of hydrophytic vegeta		wetland hydrology mus	st be pre	sent, unle	ess disturb	ped or problematio		
	e Layer (if observed):								
Type: N	IA								
Depth (ii	nches):						Hydric Soil Pr	esent? Yes X No	
Remarks:									
								CS Field Indicators of Hydric So	oils
Soil was m) March 2013 Errata. (I	nttp://www	w.nrcs.usda.gov/intern	et/FSE_	_DOCOMI	EN I S/nrcs	s142p2_051293.d	ocx).	
	.5.5.1								

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: 66 Leverett Roa	ad	City/County: Sh	utesbury	Sampling Date: 8/5/22		
Applicant/Owner: Town of Sh	nutesbury		State:	MA Sampling Point: UPL 1-2		
Investigator(s): April Dorosk,	PWS, CPSS, Fuss & O'Neill	Section, Townsh	nip, Range:			
Landform (hillside, terrace, etc	;.):	Local relief (conca	ve, convex, none):	Slope (%): 0-3		
Subregion (LRR or MLRA): LF	RR R. MLRA 144A Lat: 42.4		Long: -72.416130	Datum: NAD83		
Soil Map Unit Name:			NWI classi			
Are climatic / hydrologic condit			No X (If no, explair			
Are Vegetation X, Soil		_	Are "Normal Circumstances" p			
Are Vegetation, Soil		•	(If needed, explain any answer	rs in Remarks.)		
			int locations, transects	, important features, etc.		
Hydrophytic Vegetation Prese	ent? Yes N	lo X Is the Sam	pled Area			
Hydric Soil Present?	Yes N	lo X within a We	etland? Yes	No X		
Wetland Hydrology Present?	Yes N	lo X If yes, optio	nal Wetland Site ID: UPL 1-2			
Due to drought conditions reported for the Connecticut River Valley Region since May, hydrologic conditions are not typical for this time of year. According to the Massachsuetts Department of Conservation and Recreation (DCR) the Connecticut River Valley Region experienced drought conditions starting in May 2022 and continuing through August 2022. Plot is located in regularly mowed area.						
HYDROLOGY						
Wetland Hydrology Indicato		la a fa a a a la A		cators (minimum of two required)		
Surface Water (A1)	of one is required; check all the	riat apply) er-Stained Leaves (B9)		oil Cracks (B6) Patterns (B10)		
High Water Table (A2)		atic Fauna (B13)		Lines (B16)		
Saturation (A3)		Deposits (B15)		n Water Table (C2)		
Water Marks (B1)		rogen Sulfide Odor (C1)		urrows (C8)		
Sediment Deposits (B2)		dized Rhizospheres on Livin		Visible on Aerial Imagery (C9)		
Drift Deposits (B3)		sence of Reduced Iron (C4)	- · · · · · · · · · · · · · · · · · · ·	Stressed Plants (D1)		
Algal Mat or Crust (B4)		ent Iron Reduction in Tilled		ic Position (D2)		
Iron Deposits (B5)		Muck Surface (C7)		quitard (D3)		
Inundation Visible on Aer		er (Explain in Remarks)		graphic Relief (D4)		
Sparsely Vegetated Cond	cave Surface (B8)		FAC-Neutr	ral Test (D5)		
Field Observations:						
Surface Water Present?		epth (inches):				
Water Table Present?		epth (inches):				
Saturation Present?	Yes No X De	epth (inches):	Wetland Hydrology Presen	t? Yes No X		
(includes capillary fringe)						
Describe Recorded Data (stre	am gauge, monitoring well, a	aerial photos, previous inspe	ections), if available:			
Remarks:						
rtomano.						

VEGETATION – Use scientific names of plants. Sampling Point: **UPL 1-2** Absolute Dominant Indicator Tree Stratum (Plot size: % Cover **Dominance Test worksheet:** Species? Status 1. Number of Dominant Species 2. That Are OBL, FACW, or FAC: 0 (A) 3. **Total Number of Dominant** 4. Species Across All Strata: 1 (B) 5. Percent of Dominant Species That Are OBL, FACW, or FAC: 0.0% (A/B) Prevalence Index worksheet: =Total Cover Total % Cover of: Sapling/Shrub Stratum (Plot size: 15 OBL species x 1 = **FACW** species x 2 = 1. 2. 0 x 3 = FAC species 0 5 x 4 = 3. FACU species 2 4. UPL species x 5 = 10 5. Column Totals: 8 (A) 32 (B) 6. Prevalence Index = B/A = 4.00 **Hydrophytic Vegetation Indicators:** 7. =Total Cover 1 - Rapid Test for Hydrophytic Vegetation Herb Stratum (Plot size: _____ 5 2 - Dominance Test is >50% Galium aparine 3 - Prevalence Index is ≤3.0¹ 1. **FACU** Asclepias syriaca 2 UPL 4 - Morphological Adaptations¹ (Provide supporting data in Remarks or on a separate sheet) 1 3. Rubus hispidus No **FACW** 4. Other mowed herbaceous and grasses 82 Yes Problematic Hydrophytic Vegetation¹ (Explain) 5. ¹Indicators of hydric soil and wetland hydrology must 6. be present, unless disturbed or problematic. 7. **Definitions of Vegetation Strata:** 8. Tree - Woody plants 3 in. (7.6 cm) or more in diameter at breast height (DBH), regardless of height. Sapling/shrub - Woody plants less than 3 in. DBH and greater than or equal to 3.28 ft (1 m) tall. 11. Herb – All herbaceous (non-woody) plants, regardless 90 =Total Cover of size, and woody plants less than 3.28 ft tall. Woody Vine Stratum (Plot size: 5) Woody vines - All woody vines greater than 3.28 ft in 1. height. 2. Hydrophytic 3. Vegetation Present? Yes No X =Total Cover Remarks: (Include photo numbers here or on a separate sheet.)

SOIL Sampling Point: UPL 1-2

	escription: (Describe	to the de				or or con	firm the absence	of indicators.)	
Depth	Matrix			x Feature	es				
(inches)	Color (moist)	%	Color (moist)	%	Type ¹	Loc ²	Texture	F	Remarks
0-8	10YR 2/1	100					Loamy/Clayey		
8-12	10YR 6/3	100					Sandy		
									_
¹ Type: C=	Concentration, D=Dep	oletion, RM	1=Reduced Matrix, C	S=Cove	red or Coa	ated Sand	d Grains. ² Loo	cation: PL=Pore	Lining, M=Matrix.
	oil Indicators:	,	•					r Problematic H	
-	sol (A1)		Polyvalue Below	Surface	e (S8) (LR	RR,			, L, MLRA 149B)
	Epipedon (A2)	-	MLRA 149B)		. , .			airie Redox (A16	
	Histic (A3)		Thin Dark Surface	ce (S9) (LRR R, M	LRA 149			(S3) (LRR K, L, R)
	ogen Sulfide (A4)	-	— High Chroma Sa					e Below Surface	
	fied Layers (A5)	-	Loamy Mucky M			-		k Surface (S9) (L	
	eted Below Dark Surface	e (A11)	Loamy Gleyed N			-, -,			(F12) (LRR K, L, R)
	Dark Surface (A12)		Depleted Matrix		-,			-	s (F19) (MLRA 149B)
	y Mucky Mineral (S1)	-	Redox Dark Sur)				(1 13) (MERCA 143B)
	y Gleyed Matrix (S4)	-	Depleted Dark S					ent Material (F21)	
		-	Redox Depressi					allow Dark Surfac	
	y Redox (S5)	-		, ,					
	ed Matrix (S6)	-	Marl (F10) (LRR	K , L)			Other (E)	xplain in Remarks	5)
Dark	Surface (S7)								
³ Indicators	of hydrophytic vegeta	ition and w	etland hydrology mu	st be pre	esent, unle	ess disturl	bed or problematic		
	e Layer (if observed)								
Type:									
Depth (i	nches):						Hydric Soil Pre	esent? Yes	s No_X_
Remarks:									
	form is revised from N								rs of Hydric Soils
version 7.0	0 March 2013 Errata. (http://www	/.nrcs.usda.gov/Interr	net/FSE_	_DOCUMI	ENTS/nrc	s142p2_051293.dd	ocx)	

WETLAND DETERMINATION DATA FORM – Northcentral and Northeast Region

Project/Site: 66 Leverett Road	City/County: Shu	itesbury	Sampling Date: 8/16/22	
Applicant/Owner: Town of Shutesbury	· ·	State:	MA Sampling Point: UPL 3-4	
Investigator(s): April Dorosk, PWS, CPSS, Fuss & O'Neill	Section, Townshi	p, Range:		
Landform (hillside, terrace, etc.):	Local relief (concav	· · · · · · · · · · · · · · · · · · ·	Slope (%): 0-3	
Subregion (LRR or MLRA): LRR R, MLRA 144A Lat: 42.44		Long: -72.415961	Datum: NAD83	
Soil Map Unit Name:		NWI classi		
Are climatic / hydrologic conditions on the site typical for this	time of year? Yes	No X (If no, explair	ı in Remarks.)	
Are Vegetation X , Soil , or Hydrology si		re "Normal Circumstances" pr		
Are Vegetation, Soil, or Hydrologyn	naturally problematic? (I	f needed, explain any answer	s in Remarks.)	
SUMMARY OF FINDINGS – Attach site map sh	nowing sampling poi	nt locations, transects	, important features, etc.	
Hydrophytic Vegetation Present? Yes No	X Is the Samp	led Area		
Hydric Soil Present? Yes No			No X	
Wetland Hydrology Present? Yes No	X If yes, option	nal Wetland Site ID: UPL 3-4		
According to the Massachsuetts Department of Conservation conditions starting in May 2022 and continuing through Augustian Augustian Continuing through Contin	, ,	-		
HYDROLOGY Western Britanian Indicators		C and any ladi	to a (astronom of the monetical)	
Wetland Hydrology Indicators:	- Committee		cators (minimum of two required)	
Primary Indicators (minimum of one is required; check all that Surface Water (A1) Water	at apply) r-Stained Leaves (B9)		oil Cracks (B6) Patterns (B10)	
	tic Fauna (B13)		Lines (B16)	
 -	Deposits (B15)	Dry-Season Water Table (C2)		
l — · · · · · · — · · · · · — · · · · ·	ogen Sulfide Odor (C1)		urrows (C8)	
	zed Rhizospheres on Living		Visible on Aerial Imagery (C9)	
	ence of Reduced Iron (C4)	Stunted or Stressed Plants (D1)		
	nt Iron Reduction in Tilled S			
Iron Deposits (B5) Thin M	Muck Surface (C7)	Shallow Ac	quitard (D3)	
Inundation Visible on Aerial Imagery (B7) Other	r (Explain in Remarks)	Microtopog	graphic Relief (D4)	
Sparsely Vegetated Concave Surface (B8)		FAC-Neutr	al Test (D5)	
Field Observations:				
l —— ·	oth (inches):			
	oth (inches):	Wedler III de le De centre	10 Van Na V	
	oth (inches):	Wetland Hydrology Presen	t? Yes No_X	
(includes capillary fringe) Describe Recorded Data (stream gauge, monitoring well, ae	erial nhotos, previous inspec			
Describe Necorded Data (stream gauge, monitoring well, ac	mai priotos, previous inspec	nons, ii avallabic.		
Remarks:				


VEGETATION – Use scientific names of plants. Sampling Point: **UPL 3-4** Absolute Dominant Indicator **Dominance Test worksheet:** Tree Stratum (Plot size: % Cover Species? Status 1. Pinus strobus 40 Yes FACU Number of Dominant Species Yes 2. Fagus grandifolia 10 **FACU** That Are OBL, FACW, or FAC: 0 (A) 3. **Total Number of Dominant** 4. Species Across All Strata: 3 (B) 5. Percent of Dominant Species That Are OBL, FACW, or FAC: 0.0% 6. (A/B) Prevalence Index worksheet: 7. 50 =Total Cover Total % Cover of: Sapling/Shrub Stratum (Plot size: 15 OBL species x 1 = Kalmia latifolia **FACU FACW** species x 2 = 1. 5 0 x 3 = 2. Pinus strobus No **FACU** FAC species 0 5 x 4 = 3. Vaccinium angustifolium No **FACU** FACU species 100 0 4. UPL species x 5 = 5. Column Totals: 100 (A) 400 (B) 6. Prevalence Index = B/A = 4.00 **Hydrophytic Vegetation Indicators:** 50 =Total Cover 1 - Rapid Test for Hydrophytic Vegetation Herb Stratum (Plot size: 5) 2 - Dominance Test is >50% 1. 3 - Prevalence Index is ≤3.01 4 - Morphological Adaptations¹ (Provide supporting data in Remarks or on a separate sheet) 3. Problematic Hydrophytic Vegetation¹ (Explain) 5. ¹Indicators of hydric soil and wetland hydrology must 6. be present, unless disturbed or problematic. 7. **Definitions of Vegetation Strata:** 8. Tree - Woody plants 3 in. (7.6 cm) or more in diameter 9. at breast height (DBH), regardless of height. 10. Sapling/shrub - Woody plants less than 3 in. DBH 11. and greater than or equal to 3.28 ft (1 m) tall. Herb - All herbaceous (non-woody) plants, regardless =Total Cover of size, and woody plants less than 3.28 ft tall. Woody Vine Stratum (Plot size: _____5_) Woody vines - All woody vines greater than 3.28 ft in 1. height. 2. Hydrophytic 3. Vegetation Present? Yes No X =Total Cover Remarks: (Include photo numbers here or on a separate sheet.)

SOIL Sampling Point: UPL 3-4

	escription: (Describe	to the de	•			or or con	firm the absence	of indicators.)	
Depth	Matrix	0/		x Featur		12	T	Demonto	
(inches)	Color (moist)	<u>%</u>	Color (moist)	%	Type ¹	Loc ²	Texture	Remarks	
0-1	10YR 2/1	100					Loamy/Clayey	1-2 inches leaf litter/duff atop soil	
1-7	10YR 3/3	100					Sandy		
7-12	2.5Y 5/4	100					Sandy		
17	-Composition D-Don	lation Di	M-Daduard Matrix C	<u> </u>				antine DI - Deve Lining M-Matrix	
	Concentration, D=Depoil Indicators:	netion, Ri	vi=Reduced Matrix, C	S=Cove	rea or Coa	ated Sand		cation: PL=Pore Lining, M=Matrix. or Problematic Hydric Soils ³ :	
_	sol (A1)		Polyvalue Below	Surface	(S8) (I R	R R		ick (A10) (LRR K, L, MLRA 149B)	
	Epipedon (A2)		MLRA 149B)	Suriace	(30) (LK	κĸ,		rairie Redox (A16) (LRR K, L, R)	
			,	(CO) (IDD D M	II DA 440			
	Histic (A3)		Thin Dark Surface					icky Peat or Peat (S3) (LRR K, L, R)	
	ogen Sulfide (A4)		High Chroma Sa			-		e Below Surface (S8) (LRR K, L)	
	ied Layers (A5)		Loamy Mucky M			(, L)		rk Surface (S9) (LRR K, L)	
Deple	ted Below Dark Surfac	e (A11)	Loamy Gleyed N	/latrix (F	2)		Iron-Mar	nganese Masses (F12) (LRR K, L, R)	
Thick	Dark Surface (A12)		Depleted Matrix	(F3)			Piedmor	nt Floodplain Soils (F19) (MLRA 149B)	
Sandy	Mucky Mineral (S1)		Redox Dark Sur	face (F6)		Mesic S	podic (TA6) (MLRA 144A, 145, 149B)	
	Gleyed Matrix (S4)		Depleted Dark S					ent Material (F21)	
	Redox (S5)		Redox Depression					allow Dark Surface (TF12)	
				, ,	'		Other (Explain in Remarks)		
	ed Matrix (S6)		Marl (F10) (LRR	N , L)			Other (Explain in Remarks)		
Dark \$	Surface (S7)								
³ Indicators	of hydrophytic vegeta	tion and v	wetland hydrology mu	st be pre	esent, unle	ess disturl	bed or problemation	s.	
	e Layer (if observed)	:							
Type: N									
Depth (i	nches):						Hydric Soil Pro	esent? Yes No X	
Remarks:	form is revised from Ne	- #th t # -	al and Northagat Dagic	anal Cum	nlamant \	laraian 2	O to rofloat the ND	CC Field Indicators of Lludric Caile	
								CS Field Indicators of Hydric Soils	
version 7.0	0 March 2013 Errata. (nttp://ww	w.nrcs.usda.gov/interr	iet/FSE		=N I S/NFC	s 142p2_051293.0	ocx)	



Attachment D FEMA Information





Attachment E NRCS Custom Soil Resource Report



Natural Resources Conservation Service A product of the National Cooperative Soil Survey, a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local participants

Custom Soil Resource Report for Franklin County, Massachusetts

66 Leverett Road



Preface

Soil surveys contain information that affects land use planning in survey areas. They highlight soil limitations that affect various land uses and provide information about the properties of the soils in the survey areas. Soil surveys are designed for many different users, including farmers, ranchers, foresters, agronomists, urban planners, community officials, engineers, developers, builders, and home buyers. Also, conservationists, teachers, students, and specialists in recreation, waste disposal, and pollution control can use the surveys to help them understand, protect, or enhance the environment.

Various land use regulations of Federal, State, and local governments may impose special restrictions on land use or land treatment. Soil surveys identify soil properties that are used in making various land use or land treatment decisions. The information is intended to help the land users identify and reduce the effects of soil limitations on various land uses. The landowner or user is responsible for identifying and complying with existing laws and regulations.

Although soil survey information can be used for general farm, local, and wider area planning, onsite investigation is needed to supplement this information in some cases. Examples include soil quality assessments (http://www.nrcs.usda.gov/wps/portal/nrcs/main/soils/health/) and certain conservation and engineering applications. For more detailed information, contact your local USDA Service Center (https://offices.sc.egov.usda.gov/locator/app?agency=nrcs) or your NRCS State Soil Scientist (http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/contactus/?cid=nrcs142p2 053951).

Great differences in soil properties can occur within short distances. Some soils are seasonally wet or subject to flooding. Some are too unstable to be used as a foundation for buildings or roads. Clayey or wet soils are poorly suited to use as septic tank absorption fields. A high water table makes a soil poorly suited to basements or underground installations.

The National Cooperative Soil Survey is a joint effort of the United States Department of Agriculture and other Federal agencies, State agencies including the Agricultural Experiment Stations, and local agencies. The Natural Resources Conservation Service (NRCS) has leadership for the Federal part of the National Cooperative Soil Survey.

Information about soils is updated periodically. Updated information is available through the NRCS Web Soil Survey, the site for official soil survey information.

The U.S. Department of Agriculture (USDA) prohibits discrimination in all its programs and activities on the basis of race, color, national origin, age, disability, and where applicable, sex, marital status, familial status, parental status, religion, sexual orientation, genetic information, political beliefs, reprisal, or because all or a part of an individual's income is derived from any public assistance program. (Not all prohibited bases apply to all programs.) Persons with disabilities who require

alternative means for communication of program information (Braille, large print, audiotape, etc.) should contact USDA's TARGET Center at (202) 720-2600 (voice and TDD). To file a complaint of discrimination, write to USDA, Director, Office of Civil Rights, 1400 Independence Avenue, S.W., Washington, D.C. 20250-9410 or call (800) 795-3272 (voice) or (202) 720-6382 (TDD). USDA is an equal opportunity provider and employer.

Contents

Preface	2
How Soil Surveys Are Made	
Soil Map	
Soil Map	
Legend	
Map Unit Legend	
Map Unit Descriptions	
Franklin County, Massachusetts	13
75B—Pillsbury fine sandy loam, 0 to 8 percent slopes, very stony	13
348C—Henniker sandy loam, 8 to 15 percent slopes	14
368A—Metacomet fine sandy loam, 0 to 3 percent slopes	16
368B—Metacomet fine sandy loam, 3 to 8 percent slopes	17
444B—Chichester fine sandy loam, 3 to 8 percent slopes	19
References	21

How Soil Surveys Are Made

Soil surveys are made to provide information about the soils and miscellaneous areas in a specific area. They include a description of the soils and miscellaneous areas and their location on the landscape and tables that show soil properties and limitations affecting various uses. Soil scientists observed the steepness, length, and shape of the slopes; the general pattern of drainage; the kinds of crops and native plants; and the kinds of bedrock. They observed and described many soil profiles. A soil profile is the sequence of natural layers, or horizons, in a soil. The profile extends from the surface down into the unconsolidated material in which the soil formed or from the surface down to bedrock. The unconsolidated material is devoid of roots and other living organisms and has not been changed by other biological activity.

Currently, soils are mapped according to the boundaries of major land resource areas (MLRAs). MLRAs are geographically associated land resource units that share common characteristics related to physiography, geology, climate, water resources, soils, biological resources, and land uses (USDA, 2006). Soil survey areas typically consist of parts of one or more MLRA.

The soils and miscellaneous areas in a survey area occur in an orderly pattern that is related to the geology, landforms, relief, climate, and natural vegetation of the area. Each kind of soil and miscellaneous area is associated with a particular kind of landform or with a segment of the landform. By observing the soils and miscellaneous areas in the survey area and relating their position to specific segments of the landform, a soil scientist develops a concept, or model, of how they were formed. Thus, during mapping, this model enables the soil scientist to predict with a considerable degree of accuracy the kind of soil or miscellaneous area at a specific location on the landscape.

Commonly, individual soils on the landscape merge into one another as their characteristics gradually change. To construct an accurate soil map, however, soil scientists must determine the boundaries between the soils. They can observe only a limited number of soil profiles. Nevertheless, these observations, supplemented by an understanding of the soil-vegetation-landscape relationship, are sufficient to verify predictions of the kinds of soil in an area and to determine the boundaries.

Soil scientists recorded the characteristics of the soil profiles that they studied. They noted soil color, texture, size and shape of soil aggregates, kind and amount of rock fragments, distribution of plant roots, reaction, and other features that enable them to identify soils. After describing the soils in the survey area and determining their properties, the soil scientists assigned the soils to taxonomic classes (units). Taxonomic classes are concepts. Each taxonomic class has a set of soil characteristics with precisely defined limits. The classes are used as a basis for comparison to classify soils systematically. Soil taxonomy, the system of taxonomic classification used in the United States, is based mainly on the kind and character of soil properties and the arrangement of horizons within the profile. After the soil

scientists classified and named the soils in the survey area, they compared the individual soils with similar soils in the same taxonomic class in other areas so that they could confirm data and assemble additional data based on experience and research.

The objective of soil mapping is not to delineate pure map unit components; the objective is to separate the landscape into landforms or landform segments that have similar use and management requirements. Each map unit is defined by a unique combination of soil components and/or miscellaneous areas in predictable proportions. Some components may be highly contrasting to the other components of the map unit. The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The delineation of such landforms and landform segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, onsite investigation is needed to define and locate the soils and miscellaneous areas.

Soil scientists make many field observations in the process of producing a soil map. The frequency of observation is dependent upon several factors, including scale of mapping, intensity of mapping, design of map units, complexity of the landscape, and experience of the soil scientist. Observations are made to test and refine the soil-landscape model and predictions and to verify the classification of the soils at specific locations. Once the soil-landscape model is refined, a significantly smaller number of measurements of individual soil properties are made and recorded. These measurements may include field measurements, such as those for color, depth to bedrock, and texture, and laboratory measurements, such as those for content of sand, silt, clay, salt, and other components. Properties of each soil typically vary from one point to another across the landscape.

Observations for map unit components are aggregated to develop ranges of characteristics for the components. The aggregated values are presented. Direct measurements do not exist for every property presented for every map unit component. Values for some properties are estimated from combinations of other properties.

While a soil survey is in progress, samples of some of the soils in the area generally are collected for laboratory analyses and for engineering tests. Soil scientists interpret the data from these analyses and tests as well as the field-observed characteristics and the soil properties to determine the expected behavior of the soils under different uses. Interpretations for all of the soils are field tested through observation of the soils in different uses and under different levels of management. Some interpretations are modified to fit local conditions, and some new interpretations are developed to meet local needs. Data are assembled from other sources, such as research information, production records, and field experience of specialists. For example, data on crop yields under defined levels of management are assembled from farm records and from field or plot experiments on the same kinds of soil.

Predictions about soil behavior are based not only on soil properties but also on such variables as climate and biological activity. Soil conditions are predictable over long periods of time, but they are not predictable from year to year. For example, soil scientists can predict with a fairly high degree of accuracy that a given soil will have a high water table within certain depths in most years, but they cannot predict that a high water table will always be at a specific level in the soil on a specific date.

After soil scientists located and identified the significant natural bodies of soil in the survey area, they drew the boundaries of these bodies on aerial photographs and

identified each as a specific map unit. Aerial photographs show trees, buildings, fields, roads, and rivers, all of which help in locating boundaries accurately.

Soil Map

The soil map section includes the soil map for the defined area of interest, a list of soil map units on the map and extent of each map unit, and cartographic symbols displayed on the map. Also presented are various metadata about data used to produce the map, and a description of each soil map unit.



MAP LEGEND

Area of Interest (AOI)

Area of Interest (AOI)

Soils

Soil Map Unit Polygons

-

Soil Map Unit Lines

Soil Map Unit Points

Special Point Features

ဖ

Blowout

 \boxtimes

Borrow Pit

Ж

Clay Spot

^

Closed Depression

~

'

4.0

Gravel Pit

00

Gravelly Spot

0

Landfill Lava Flow

٨.

Marsh or swamp

2

Mine or Quarry

0

Miscellaneous Water
Perennial Water

0

Rock Outcrop

+

Saline Spot

. .

Sandy Spot

Sodic Spot

0

Severely Eroded Spot

Sinkhole

Slide or Slip

Ø

8

Spoil Area Stony Spot

٥

Very Stony Spot

Ø

Wet Spot Other

Δ

Special Line Features

Water Features

_

Streams and Canals

Transportation

ransp

Rails

~

Interstate Highways

~

US Routes

 \sim

Major Roads

~

Local Roads

Background

10

Aerial Photography

MAP INFORMATION

The soil surveys that comprise your AOI were mapped at 1:12.000.

Warning: Soil Map may not be valid at this scale.

Enlargement of maps beyond the scale of mapping can cause misunderstanding of the detail of mapping and accuracy of soil line placement. The maps do not show the small areas of contrasting soils that could have been shown at a more detailed scale.

Please rely on the bar scale on each map sheet for map measurements.

Source of Map: Natural Resources Conservation Service

Web Soil Survey URL:

Coordinate System: Web Mercator (EPSG:3857)

Maps from the Web Soil Survey are based on the Web Mercator projection, which preserves direction and shape but distorts distance and area. A projection that preserves area, such as the Albers equal-area conic projection, should be used if more accurate calculations of distance or area are required.

This product is generated from the USDA-NRCS certified data as of the version date(s) listed below.

Soil Survey Area: Franklin County, Massachusetts Survey Area Data: Version 16, Sep 2, 2021

Soil map units are labeled (as space allows) for map scales 1:50.000 or larger.

Date(s) aerial images were photographed: Oct 15, 2020—Oct 31, 2020

The orthophoto or other base map on which the soil lines were compiled and digitized probably differs from the background imagery displayed on these maps. As a result, some minor shifting of map unit boundaries may be evident.

Map Unit Legend

Map Unit Symbol	Map Unit Name	Acres in AOI	Percent of AOI
75B	Pillsbury fine sandy loam, 0 to 8 percent slopes, very stony	2.2	10.8%
348C	Henniker sandy loam, 8 to 15 percent slopes	1.5	7.4%
368A	Metacomet fine sandy loam, 0 to 3 percent slopes	14.5	70.6%
368B	Metacomet fine sandy loam, 3 to 8 percent slopes	2.0	9.9%
444B	Chichester fine sandy loam, 3 to 8 percent slopes	0.3	1.3%
Totals for Area of Interest	,	20.5	100.0%

Map Unit Descriptions

The map units delineated on the detailed soil maps in a soil survey represent the soils or miscellaneous areas in the survey area. The map unit descriptions, along with the maps, can be used to determine the composition and properties of a unit.

A map unit delineation on a soil map represents an area dominated by one or more major kinds of soil or miscellaneous areas. A map unit is identified and named according to the taxonomic classification of the dominant soils. Within a taxonomic class there are precisely defined limits for the properties of the soils. On the landscape, however, the soils are natural phenomena, and they have the characteristic variability of all natural phenomena. Thus, the range of some observed properties may extend beyond the limits defined for a taxonomic class. Areas of soils of a single taxonomic class rarely, if ever, can be mapped without including areas of other taxonomic classes. Consequently, every map unit is made up of the soils or miscellaneous areas for which it is named and some minor components that belong to taxonomic classes other than those of the major soils.

Most minor soils have properties similar to those of the dominant soil or soils in the map unit, and thus they do not affect use and management. These are called noncontrasting, or similar, components. They may or may not be mentioned in a particular map unit description. Other minor components, however, have properties and behavioral characteristics divergent enough to affect use or to require different management. These are called contrasting, or dissimilar, components. They generally are in small areas and could not be mapped separately because of the scale used. Some small areas of strongly contrasting soils or miscellaneous areas are identified by a special symbol on the maps. If included in the database for a given area, the contrasting minor components are identified in the map unit descriptions along with some characteristics of each. A few areas of minor components may not have been observed, and consequently they are not mentioned in the descriptions, especially where the pattern was so complex that it was impractical to make enough observations to identify all the soils and miscellaneous areas on the landscape.

The presence of minor components in a map unit in no way diminishes the usefulness or accuracy of the data. The objective of mapping is not to delineate pure taxonomic classes but rather to separate the landscape into landforms or landform segments that have similar use and management requirements. The delineation of such segments on the map provides sufficient information for the development of resource plans. If intensive use of small areas is planned, however, onsite investigation is needed to define and locate the soils and miscellaneous areas.

An identifying symbol precedes the map unit name in the map unit descriptions. Each description includes general facts about the unit and gives important soil properties and qualities.

Soils that have profiles that are almost alike make up a *soil series*. Except for differences in texture of the surface layer, all the soils of a series have major horizons that are similar in composition, thickness, and arrangement.

Soils of one series can differ in texture of the surface layer, slope, stoniness, salinity, degree of erosion, and other characteristics that affect their use. On the basis of such differences, a soil series is divided into *soil phases*. Most of the areas shown on the detailed soil maps are phases of soil series. The name of a soil phase commonly indicates a feature that affects use or management. For example, Alpha silt loam, 0 to 2 percent slopes, is a phase of the Alpha series.

Some map units are made up of two or more major soils or miscellaneous areas. These map units are complexes, associations, or undifferentiated groups.

A *complex* consists of two or more soils or miscellaneous areas in such an intricate pattern or in such small areas that they cannot be shown separately on the maps. The pattern and proportion of the soils or miscellaneous areas are somewhat similar in all areas. Alpha-Beta complex, 0 to 6 percent slopes, is an example.

An *association* is made up of two or more geographically associated soils or miscellaneous areas that are shown as one unit on the maps. Because of present or anticipated uses of the map units in the survey area, it was not considered practical or necessary to map the soils or miscellaneous areas separately. The pattern and relative proportion of the soils or miscellaneous areas are somewhat similar. Alpha-Beta association, 0 to 2 percent slopes, is an example.

An *undifferentiated group* is made up of two or more soils or miscellaneous areas that could be mapped individually but are mapped as one unit because similar interpretations can be made for use and management. The pattern and proportion of the soils or miscellaneous areas in a mapped area are not uniform. An area can be made up of only one of the major soils or miscellaneous areas, or it can be made up of all of them. Alpha and Beta soils, 0 to 2 percent slopes, is an example.

Some surveys include *miscellaneous areas*. Such areas have little or no soil material and support little or no vegetation. Rock outcrop is an example.

Franklin County, Massachusetts

75B—Pillsbury fine sandy loam, 0 to 8 percent slopes, very stony

Map Unit Setting

National map unit symbol: 2ty6x Elevation: 360 to 2,070 feet

Mean annual precipitation: 31 to 95 inches Mean annual air temperature: 27 to 52 degrees F

Frost-free period: 90 to 140 days

Farmland classification: Not prime farmland

Map Unit Composition

Pillsbury, very stony, and similar soils: 79 percent

Minor components: 21 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Pillsbury, Very Stony

Setting

Landform: Mountains, hills

Landform position (two-dimensional): Toeslope, footslope

Landform position (three-dimensional): Mountainbase, base slope, interfluve

Down-slope shape: Concave Across-slope shape: Concave

Parent material: Loamy lodgment till derived from gneiss and/or loamy lodgment till derived from mica schist and/or loamy lodgment till derived from granite

Typical profile

Oe - 0 to 1 inches: mucky peat A - 1 to 6 inches: fine sandy loam

Bg1 - 6 to 13 inches: cobbly fine sandy loam Bg2 - 13 to 23 inches: cobbly fine sandy loam Cd - 23 to 65 inches: cobbly fine sandy loam

Properties and qualities

Slope: 0 to 8 percent

Surface area covered with cobbles, stones or boulders: 1.1 percent Depth to restrictive feature: 21 to 43 inches to densic material

Drainage class: Poorly drained

Capacity of the most limiting layer to transmit water (Ksat): Moderately low to

moderately high (0.01 to 1.42 in/hr)

Depth to water table: About 0 to 12 inches

Frequency of flooding: None Frequency of ponding: None

Maximum salinity: Nonsaline (0.0 to 1.9 mmhos/cm)

Available water supply, 0 to 60 inches: Low (about 3.3 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 6s

Hydrologic Soil Group: D

Ecological site: F144BY305ME - Wet Loamy Flat

Hydric soil rating: Yes

Minor Components

Peru, very stony

Percent of map unit: 9 percent Landform: Mountains, hills

Landform position (two-dimensional): Backslope, footslope

Landform position (three-dimensional): Mountainbase, interfluve, base slope

Microfeatures of landform position: Rises, rises

Down-slope shape: Convex

Across-slope shape: Linear, convex

Hydric soil rating: No

Peacham, very stony

Percent of map unit: 5 percent Landform: Hills, mountains

Landform position (two-dimensional): Toeslope, footslope

Landform position (three-dimensional): Mountainbase, interfluve, base slope Microfeatures of landform position: Closed depressions, closed depressions

Down-slope shape: Concave Across-slope shape: Concave

Hydric soil rating: Yes

Wonsqueak

Percent of map unit: 4 percent Landform: Hills, mountains

Landform position (two-dimensional): Toeslope, footslope

Landform position (three-dimensional): Mountainbase, base slope, interfluve Microfeatures of landform position: Closed depressions, closed depressions

Down-slope shape: Concave Across-slope shape: Concave

Hydric soil rating: Yes

Lyman, very stony

Percent of map unit: 3 percent Landform: Mountains, hills

Landform position (two-dimensional): Backslope, shoulder, summit

Landform position (three-dimensional): Mountainbase, interfluve, base slope

Microfeatures of landform position: Rises, rises

Down-slope shape: Convex Across-slope shape: Convex

Hydric soil rating: No

348C—Henniker sandy loam, 8 to 15 percent slopes

Map Unit Setting

National map unit symbol: 9cdv Elevation: 920 to 1,280 feet

Mean annual precipitation: 39 to 53 inches
Mean annual air temperature: 34 to 56 degrees F

Frost-free period: 140 to 174 days

Farmland classification: Farmland of statewide importance

Map Unit Composition

Henniker and similar soils: 83 percent Minor components: 17 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Henniker

Setting

Landform: Drumlins, ground moraines

Landform position (two-dimensional): Backslope, toeslope

Landform position (three-dimensional): Side slope

Down-slope shape: Linear, convex Across-slope shape: Convex, linear

Parent material: Loamy till underlain by sandy lodgment till derived from gneiss

Typical profile

Oi - 0 to 0 inches: slightly decomposed plant material Oe - 0 to 1 inches: moderately decomposed plant material

Ap - 1 to 8 inches: sandy loam
Bw1 - 8 to 15 inches: sandy loam
Bw2 - 15 to 24 inches: sandy loam
BC - 24 to 29 inches: cobbly sandy loam
Cd1 - 29 to 39 inches: loamy sand
Cd2 - 39 to 45 inches: loamy sand
Cd3 - 45 to 65 inches: loamy sand

Properties and qualities

Slope: 8 to 15 percent

Surface area covered with cobbles, stones or boulders: 0.0 percent Depth to restrictive feature: 18 to 36 inches to densic material

Drainage class: Well drained Runoff class: Medium

Capacity of the most limiting layer to transmit water (Ksat): Very low to moderately

high (0.00 to 0.20 in/hr)

Depth to water table: About 13 to 31 inches

Frequency of flooding: None Frequency of ponding: None

Available water supply, 0 to 60 inches: Low (about 3.6 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 3e

Hydrologic Soil Group: B

Ecological site: F144BY501ME - Loamy Slope (Northern Hardwoods)

Hydric soil rating: No

Minor Components

Metacomet

Percent of map unit: 10 percent Landform: Drumlins, ground moraines

Landform position (two-dimensional): Backslope Landform position (three-dimensional): Side slope

Down-slope shape: Linear Across-slope shape: Convex

Hydric soil rating: No

Chichester

Percent of map unit: 5 percent

Landform: Ground moraines, valley sides

Landform position (two-dimensional): Backslope, footslope Landform position (three-dimensional): Side slope, base slope

Down-slope shape: Concave, linear Across-slope shape: Convex, linear

Hydric soil rating: No

Pillsbury

Percent of map unit: 2 percent Landform: Drumlins, ground moraines

Landform position (two-dimensional): Backslope Landform position (three-dimensional): Base slope

Down-slope shape: Concave Across-slope shape: Concave

Hydric soil rating: Yes

368A—Metacomet fine sandy loam, 0 to 3 percent slopes

Map Unit Setting

National map unit symbol: 9cck Elevation: 970 to 1,250 feet

Mean annual precipitation: 39 to 53 inches
Mean annual air temperature: 34 to 56 degrees F

Frost-free period: 140 to 174 days

Farmland classification: All areas are prime farmland

Map Unit Composition

Metacomet and similar soils: 95 percent

Minor components: 5 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Metacomet

Setting

Landform: Drumlins, ground moraines

Landform position (two-dimensional): Backslope Landform position (three-dimensional): Side slope

Down-slope shape: Linear Across-slope shape: Convex

Parent material: Loamy till underlain by sandy lodgment till derived from gneiss

Typical profile

Oi - 0 to 2 inches: slightly decomposed plant material
Oe - 2 to 2 inches: moderately decomposed plant material

A - 2 to 5 inches: fine sandy loam
E - 5 to 6 inches: fine sandy loam
Bw1 - 6 to 13 inches: fine sandy loam

Bw2 - 13 to 18 inches: fine sandy loam Bw3 - 18 to 27 inches: sandy loam C - 27 to 32 inches: stony loamy sand Cd1 - 32 to 48 inches: loamy sand Cd2 - 48 to 65 inches: sandy loam

Properties and qualities

Slope: 0 to 3 percent

Surface area covered with cobbles, stones or boulders: 0.0 percent Depth to restrictive feature: 20 to 37 inches to densic material

Drainage class: Moderately well drained

Runoff class: Very high

Capacity of the most limiting layer to transmit water (Ksat): Very low to moderately

high (0.00 to 0.20 in/hr)

Depth to water table: About 16 to 24 inches

Frequency of flooding: None Frequency of ponding: None

Available water supply, 0 to 60 inches: Low (about 4.9 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 2w

Hydrologic Soil Group: B/D

Ecological site: F144BY501ME - Loamy Slope (Northern Hardwoods)

Hydric soil rating: No

Minor Components

Pillsbury

Percent of map unit: 5 percent

Landform: Ground moraines, drumlins

Landform position (two-dimensional): Backslope Landform position (three-dimensional): Base slope

Down-slope shape: Concave Across-slope shape: Concave

Hydric soil rating: Yes

368B—Metacomet fine sandy loam, 3 to 8 percent slopes

Map Unit Setting

National map unit symbol: 9ccj Elevation: 960 to 1,260 feet

Mean annual precipitation: 39 to 53 inches
Mean annual air temperature: 34 to 56 degrees F

Frost-free period: 140 to 174 days

Farmland classification: All areas are prime farmland

Map Unit Composition

Metacomet and similar soils: 85 percent

Minor components: 15 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Metacomet

Setting

Landform: Drumlins, ground moraines

Landform position (two-dimensional): Backslope Landform position (three-dimensional): Side slope

Down-slope shape: Linear Across-slope shape: Convex

Parent material: Loamy till underlain by sandy lodgment till derived from gneiss

Typical profile

Oi - 0 to 2 inches: slightly decomposed plant material
Oe - 2 to 2 inches: moderately decomposed plant material

A - 2 to 5 inches: fine sandy loam
E - 5 to 6 inches: fine sandy loam
Bw1 - 6 to 13 inches: fine sandy loam
Bw2 - 13 to 18 inches: fine sandy loam
Bw3 - 18 to 27 inches: sandy loam
C - 27 to 32 inches: stony loamy sand
Cd1 - 32 to 48 inches: loamy sand
Cd2 - 48 to 65 inches: sandy loam

Properties and qualities

Slope: 3 to 8 percent

Surface area covered with cobbles, stones or boulders: 0.0 percent Depth to restrictive feature: 20 to 37 inches to densic material

Drainage class: Moderately well drained

Runoff class: Very high

Capacity of the most limiting layer to transmit water (Ksat): Very low to moderately

high (0.00 to 0.20 in/hr)

Depth to water table: About 16 to 24 inches

Frequency of flooding: None Frequency of ponding: None

Available water supply, 0 to 60 inches: Low (about 4.9 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 2e

Hydrologic Soil Group: B/D

Ecological site: F144BY501ME - Loamy Slope (Northern Hardwoods)

Hydric soil rating: No

Minor Components

Pillsbury

Percent of map unit: 10 percent Landform: Drumlins, ground moraines

Landform position (two-dimensional): Backslope Landform position (three-dimensional): Base slope

Down-slope shape: Concave Across-slope shape: Concave Hydric soil rating: Yes

Henniker

Percent of map unit: 5 percent

Landform: Drumlins, ground moraines

Landform position (two-dimensional): Backslope, toeslope

Landform position (three-dimensional): Side slope

Down-slope shape: Linear, convex Across-slope shape: Convex, linear

Hydric soil rating: No

444B—Chichester fine sandy loam, 3 to 8 percent slopes

Map Unit Setting

National map unit symbol: 9cfm Elevation: 940 to 1.400 feet

Mean annual precipitation: 39 to 53 inches Mean annual air temperature: 34 to 56 degrees F

Frost-free period: 140 to 174 days

Farmland classification: All areas are prime farmland

Map Unit Composition

Chichester and similar soils: 85 percent

Minor components: 15 percent

Estimates are based on observations, descriptions, and transects of the mapunit.

Description of Chichester

Setting

Landform: Ground moraines, valley sides

Landform position (two-dimensional): Backslope, footslope Landform position (three-dimensional): Side slope, base slope

Down-slope shape: Concave, linear Across-slope shape: Convex, linear

Parent material: Loamy over sandy supraglacial meltout till derived from gneiss

Typical profile

Oe - 0 to 1 inches: moderately decomposed plant material

A - 1 to 3 inches: fine sandy loam

Ap - 3 to 7 inches: fine sandy loam

Bw1 - 7 to 10 inches: fine sandy loam

Bw2 - 10 to 20 inches: fine sandy loam

C1 - 20 to 28 inches: gravelly loamy coarse sand

C2 - 28 to 35 inches: sand C3 - 35 to 44 inches: stony sand C4 - 44 to 65 inches: stony sand

Properties and qualities

Slope: 3 to 8 percent

Surface area covered with cobbles, stones or boulders: 0.0 percent

Depth to restrictive feature: More than 80 inches

Drainage class: Well drained

Runoff class: Low

Capacity of the most limiting layer to transmit water (Ksat): Moderately high to high

(0.20 to 6.00 in/hr)

Depth to water table: More than 80 inches

Frequency of flooding: None Frequency of ponding: None

Available water supply, 0 to 60 inches: Low (about 3.5 inches)

Interpretive groups

Land capability classification (irrigated): None specified

Land capability classification (nonirrigated): 2e

Hydrologic Soil Group: A

Ecological site: F144BY505ME - Loamy over Sandy

Hydric soil rating: No

Minor Components

Henniker

Percent of map unit: 10 percent Landform: Drumlins, ground moraines

Landform position (two-dimensional): Backslope, toeslope

Landform position (three-dimensional): Side slope

Down-slope shape: Linear, convex Across-slope shape: Convex, linear

Hydric soil rating: No

Millsite

Percent of map unit: 5 percent

Landform: Hills

Landform position (two-dimensional): Backslope

Landform position (three-dimensional): Mountainflank, side slope

Down-slope shape: Convex Across-slope shape: Linear Hydric soil rating: No

References

American Association of State Highway and Transportation Officials (AASHTO). 2004. Standard specifications for transportation materials and methods of sampling and testing. 24th edition.

American Society for Testing and Materials (ASTM). 2005. Standard classification of soils for engineering purposes. ASTM Standard D2487-00.

Cowardin, L.M., V. Carter, F.C. Golet, and E.T. LaRoe. 1979. Classification of wetlands and deep-water habitats of the United States. U.S. Fish and Wildlife Service FWS/OBS-79/31.

Federal Register. July 13, 1994. Changes in hydric soils of the United States.

Federal Register. September 18, 2002. Hydric soils of the United States.

Hurt, G.W., and L.M. Vasilas, editors. Version 6.0, 2006. Field indicators of hydric soils in the United States.

National Research Council. 1995. Wetlands: Characteristics and boundaries.

Soil Survey Division Staff. 1993. Soil survey manual. Soil Conservation Service. U.S. Department of Agriculture Handbook 18. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_054262

Soil Survey Staff. 1999. Soil taxonomy: A basic system of soil classification for making and interpreting soil surveys. 2nd edition. Natural Resources Conservation Service, U.S. Department of Agriculture Handbook 436. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2 053577

Soil Survey Staff. 2010. Keys to soil taxonomy. 11th edition. U.S. Department of Agriculture, Natural Resources Conservation Service. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2 053580

Tiner, R.W., Jr. 1985. Wetlands of Delaware. U.S. Fish and Wildlife Service and Delaware Department of Natural Resources and Environmental Control, Wetlands Section.

United States Army Corps of Engineers, Environmental Laboratory. 1987. Corps of Engineers wetlands delineation manual. Waterways Experiment Station Technical Report Y-87-1.

United States Department of Agriculture, Natural Resources Conservation Service. National forestry manual. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/home/?cid=nrcs142p2 053374

United States Department of Agriculture, Natural Resources Conservation Service. National range and pasture handbook. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/landuse/rangepasture/?cid=stelprdb1043084

United States Department of Agriculture, Natural Resources Conservation Service. National soil survey handbook, title 430-VI. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/soils/scientists/?cid=nrcs142p2_054242

United States Department of Agriculture, Natural Resources Conservation Service. 2006. Land resource regions and major land resource areas of the United States, the Caribbean, and the Pacific Basin. U.S. Department of Agriculture Handbook 296. http://www.nrcs.usda.gov/wps/portal/nrcs/detail/national/soils/?cid=nrcs142p2_053624

United States Department of Agriculture, Soil Conservation Service. 1961. Land capability classification. U.S. Department of Agriculture Handbook 210. http://www.nrcs.usda.gov/Internet/FSE_DOCUMENTS/nrcs142p2_052290.pdf



Massachusetts Department of Environmental Protection

eDEP Transaction Copy

Here is the file you requested for your records.

To retain a copy of this file you must save and/or print.

Username: 286LINDA

Transaction ID: 1526533

Document: WPA Form 4B - ORAD

Size of File: 88.52K

Status of Transaction: Submitted

Date and Time Created: 3/9/2023:10:26:05 PM

Note: This file only includes forms that were part of your transaction as of the date and time indicated above. If you need a more current copy of your transaction, return to eDEP and select to "Download a Copy" from the Current Submittals page.

Massachusetts Department of Environmental Protection Provided by MassDEP: Number of Proceedings Protection Watlands MassDEP File #:286.0

Bureau of Resource Protection - Wetlands

WPA Form 4B - Order of Resource Area Delineation

Massachusetts Wetlands Protection Act M.G.L. c. 131 S40

Provided by MassDEP: MassDEP File #:286-0297 eDEP Transaction #:1526533 City/Town:SHUTESBURY

A. General Information

- 1. Conservation Commission SHUTESBURY
- 2. This Issuance is for (Check one):

 - b.
 Amended Order of Resource Area Delineation
- 3. Applicant Details

a. First Name
b. Last Name
c. Organization
TOWN OF SHUTESBURY; ATTN: MARY ANNE ANTONELLIS

d. Mailing Address 10 COOLEYVILLE ROAD, PO BOX 256

e. City/Town SHUTESBURY f. State MA g. ZIP 01072

4. Property Owner (if different from applicant):

a. First Name b. Last Name

c. Organization

d. Mailing Address

e. City/Town f. State g. ZIP

5. Project Location

a. Street Address 66 LEVERETT ROAD

b. City/Town SHUTESBURY c. Zip 01072 d. Assessors Map/Plat# O e. Parcel/Lot# 32

f. Latitude 42.45094N g. Longitude 72.41611W

6. Dates

a. Date ANRAD Filed 9/30/2022 b. Date Public Hearing Closed 3/9/2023 c. Date Of Issuance 3/10/2023

7. Final Approved Plans and Other Documents

Plan Title	Plan Prepared By	Plan Signed By	Plan Final Date	Plan Scale
"WETLAND FLAG LOCATIONS 66 LEVERETT ROAD SHUTESBURY,	FUSS &		February 2023	
MASSACHUSETTS", FIGURES 3-1 AND 3-2	O'NEILL		(last revised)	
"WETLAND DELINEATION OVERVIEW 66 LEVERETT ROAD	FUSS &		February 2023	
SHUTESBURY, MASACHUSETTS", FIGURE 2	O'NEILL		(last revised)	

B. Order of Delineation

- 1. The Conservation Commission has determined the following (check whichever is applicable)
- a. \Box **Accurate:** The boundaries described on the referenced plan(s) above and in the Abbreviated Notice of Resource Area Delineation are accurately drawn for the following resource area(s):
 - 1. ☐ Bordering Vegetated Wetlands
- 2. \square Other resource area(s), specifically

a.

b. Modified: The boundaries described on the plan(s) referenced above, as modified by the Conservation Commission from the

Massachusetts Department of Environmental Protection

Bureau of Resource Protection - Wetlands

Provided by MassDEP:

MassDEP File #:286-02

WPA Form 4B - Order of Resource Area Delineation

Massachusetts Wetlands Protection Act M.G.L. c. 131 S40

Provided by MassDEP: MassDEP File #:286-0297 eDEP Transaction #:1526533 City/Town:SHUTESBURY

plans contained in the Abbreviated Notice of Resource Area Delineation, are accurately drawn from the following resource area(s):

- 1. **☑** Bordering Vegetated Wetlands
- 2. ▼ Other resource area(s), specifically a.PLEASE SEE ATTACHED FINDINGS.
- c. \Box Inaccurate:: The boundaries described on the referenced plan(s) and in the Abbreviated Notice of Recource Area Delineation were found to be inaccurate and cannot be confirmed for the following resource area(s):
 - 1.

 Bordering Vegetated Wetlands
- 2. ☐ Other resource area(s), specifically

a.

3. The boundaries were determined to be inaccurate because:

C. Findings

This Order of Resource Area Delineation determines that the boundaries of those resource areas noted above, have been delineated and approved by the Commission and are binding as to all decisions rendered pursuant to the Massachusetts Wetlands Protection Act (M.G.L. c.131, S 40) and its regulations (310 CMR 10.00). This Order does not, however, determine the boundaries of any resource area or Buffer Zone to any resource area not specifically noted above, regardless of whether such boundaries are contained on the plans attached to this Order or to the Abbreviated Notice of Resource Area Delineation. This Order must be signed by a majority of the Conservation Commission. The Order must be sent by certified mail (return receipt requested) or hand delivered to the applicant. A copy also must be mailed or hand delivered at the same time to the appropriate DEP Regional Office (see http://www.mass.gov/dep/about/region/findyour.htm).

D. Appeals

The applicant, the owner, any person aggrieved by this Order, any owner of land abutting the land subject to this Order, or any ten residents of the city or town in which such land is located, are hereby notified of their right to request the appropriate DEP Regional Office to issue a Superseding Order of Resource Area Delineation. When requested to issue a Superseding Order of Resource Area Delineation, the Department's review is limited to the objections to the resource area delineation(s) stated in the appeal request. The request must be made by certified mail or hand delivery to the Department, with the appropriate filing fee and a completed Request for Departmental Action Fee Transmittal Form, as provided in 310 CMR 10.03(7) within ten business days from the date of issuance of this Order. A copy of the request shall at the same time be sent by certified mail or hand delivery to the Conservation Commission and to the applicant, if he/she is not the appellant. Any appellants seeking to appeal the Department?s Superseding Order of Resource Area Delineation will be required to demonstrate prior participation in the review of this project. Previous participation in the permit proceeding means the submission of written information to the Conservation Commission prior to the close of the public hearing, requesting a Superseding Order or Determination, or providing written information to the Department prior to issuance of a Superseding Order or Determination. The request shall state clearly and concisely the objections to the Order which is being appealed and how the Order does not contribute to the protection of the interests identified in the Massachusetts Wetlands Protection Act, (M.G.L. c. 131, S 40) and is inconsistent with the wetlands regulations (310 CMR 10.00). To the extent that the Order is based on a municipal bylaw or ordinance, and not on the Massachusetts Wetlands Protection Act or regulations, the Department of Environmental Protection has no appellate jurisdiction.

Massachusetts Department of Environmental ProtectionProvided by MassDEP:Bureau of Resource Protection - WetlandsMassDEP File #:286-0297

WPA Form 4B - Order of Resource Area Delineation


eDEP Transaction #:1526533 City/Town:SHUTESBURY

E. Signatures	 Date of Original Order No. of Signatures required 5
Miriam DeFant	Beth Willson
Mary David	
Robin Harrington	
Scott Kahan	See attached Certificate of Vote authorizing digital signatures.
This Order is valid for three years from the	he date of issuance.
	Order of Resource Area Delineation, this Order does not extend the issuance date of ded Order will expire on the date of the Original Final Order unless extended in writing
This Order is issued to the applicant and the pr	roperty owner (if different) as follows:
3. By hand delivery on	4. ☐ By certified mail, return receipt requested on
a. Date3/10/2023	a. Date

CERTIFICATE OF VOTE AUTHORIZING SIGNATURES PURSUANT TO M.G.L. c.110G

On May 14, 2020, the Shutesbury Conservation Commission met in open session through publicly accessible video-conference software, pursuant to the "Order Suspending Certain Provisions of the Open Meeting Law, G.L. c. 30A, §20," issued by Governor Charles D. Baker on March 12, 2020. At this duly held meeting, the following action was taken:

Motion: Shutesbury Conservation Commission hereby recognizes and accepts the provisions of M.G.L. c.110G regarding electronic signatures and that its members will henceforth execute documents either with electronic signatures or with wet ink signatures and that both will carry the same legal weight and effect. Motion was seconded.



Roll Call vote:



Shutesbury Conservation Commission Attachment for ORAD at 66 Leverett Road (Lot O-32) DEP File # 286-0297

Date: March 10, 2023 Lot: Map 0, LOT 32

Applicant: Town of Shutesbury
Landowners: Town of Shutesbury

These findings are based on the figure set "Wetland Flag Locations 66 Leverett Road Shutesbury, Massachusetts" Figure 3-1 and 3-2 and "Wetland Delineation Overview 66 Leverett Road Shutesbury, Massachusetts" Figure 2 prepared by Fuss and O'Neill February 2023 (last revised).

- 1. This Order of Resource Area Delineation is hereby issued pursuant to the Conservation Commission's jurisdiction over Resource Areas as defined by the Wetlands Protection Act (MGL Chapter 131, § 40), the Wetlands Protection Act Regulations (310 CMR 10.00), and Shutesbury General Wetlands Protection Bylaw and Bylaw Regulations.
- 2. The Shutesbury Conservation Commission approves the boundaries of Bordering Vegetated Wetlands depicted on the final site plans "Wetland Flag Locations 66 Leverett Road Shutesbury, Massachusetts" Figure 3-1 and 3-2 prepared by Fuss and O'Neill February 2023 (last revised).
- 3. The Commission does not approve any Protected Resource Area boundaries located outside of the depicted ANRAD Review Area boundary on the final site plans.
- 4. The following findings concern jurisdictional areas protected by both the Massachusetts Wetlands Protection Act and the Shutesbury General Wetland Protection Bylaw ("the Bylaw":
 - The Commission approves the boundary of 100-foot Buffer Zones within the ANRAD Review Area boundary, including the no-contest Buffer Zone boundaries, but <u>excluding</u> the Buffer Zone boundary associated with the BVW boundary between flags wf 3a-114 and wf 3a-115. The BVW boundary between flags wf 3a-114 and wf 3a-115 has not been established, reviewed, and approved. Therefore, the associated Buffer Zone boundary has not been established, reviewed, and approved. Any Buffer Zone for this Resource Area depicted on the site plan is not approved.
 - The Commission approves the boundary of the Bordering Vegetated Wetland BVW 1 demarcated by flags wf 1a-100 through and including wf 1a-133.
 - The Commission approves the boundary of the Bordering Vegetated Wetland BVW 2 extending from the property lines and demarcated by flags wf 2a-101 through and including wf 2a-105.
 - The Commission finds that the BVW 2 has been impacted by the unauthorized, post-1965 and 1972 placement of a fill pile within the BVW as noted on Page 5 of the "Massachusetts Inland Resource Area Delineation Report" prepared by Fuss and O'Neill (last revised February 1, 2023).

- The Commission finds that the BVW 2 must be restored.
- The Commission approves the boundary of the Bordering Vegetated Wetland BVW 3 extending from the property lines and demarcated by flags wf 3b-101 through and including wf 3b-113 (joins wf 3a-100); wf 3a-100 through and including wf 3a-114; and wf 3a-115 through and including wf 3a-117. The Commission does <u>not</u> approve the BVW boundary between flags wf 3a-114 and wf 3a-115.
- The Commission finds that the BVW proximal to flags wf 3a-114 and wf 3a-115 has been impacted by the unauthorized, post-1965 and 1972 placement of fill within the BVW.
- The Commission finds that the BVW proximal to flags wf 3a-114 and wf 3a-115 must be restored and the BVW boundary established per 310 CMR 10.55(2)(c)3.
- The Commission finds that Isolated Vegetated Wetlands (IVWs) 4, 5, 6 and 7 do not meet the definition of Isolated Land Subject to Flooding under 310 CMR 10.57(2)(b)1.
- 5. The following findings concern the jurisdictional areas protected by the Shutesbury General Wetland Protection Bylaw:
 - The Commission approves the boundary of 100-foot Buffer Zones within the ANRAD Review Area boundary, including the no-contest Buffer Zone boundaries, but **excluding** the Buffer Zone boundary associated with the BVW boundary between flags wf 3a-114 and wf 3a-115. The BVW boundary between flags wf 3a-114 and wf 3a-115 has not been established, reviewed, and approved. Therefore, the associated Buffer Zone boundary has not been established, reviewed, and approved.
 - Buffer Zones are protected as Resource Areas under the Bylaw.
 - The Commission finds that Isolated Vegetated Wetlands (IVWs) 4, 5, 6 and 7 do not meet the size criteria for protection as Isolated Vegetated Wetlands under the Shutesbury Wetlands Bylaw Regulations.
 - Subsurface lakes, rivers, ponds, and streams are protected as Resource Areas under the Bylaw. The boundaries of subsurface lakes, rivers, ponds, and streams have not been delineated and are not approved by the Commission.
 - The areas within 100 feet of subsurface lakes, rivers, ponds, and streams are protected as Resource Areas under the Bylaw. The boundaries of areas within 100 feet of subsurface lakes, rivers, ponds, and streams have not been delineated and are not approved by the Commission.
 - If a Notice of Intent is required for work within the ANRAD Review Area boundary, the applicant must submit a site plan depicting all jurisdictional Resource Area boundaries under the Bylaw, those approved under this ORAD and those present but not reviewed and approved under this ORAD.
- 6. A southeasterly portion of the ANRAD Review Area is located within a mapped Outstanding Resource Area associated with the Quabbin Reservoir Public Water Supply Watershed.

Town of Shutesbury

Conservation Commission

Provided by MassDEP: 286-0297

MassDEP File Number

eDEP Transaction Number

Form 4B - Order of Resource Area Delineation

Shutesbury General Wetlands Protection Bylaw

A. General Information

Shutesbury
City/Town

Fro	TT1"	esbury servation Commission		
	i. Con	iservation Commission		
2.	This Issuand	ce is for (check one):		
	a. 🛭 Ord	er of Resource Area Deline	eation	
	b. Ame	ended Order of Resource A	Area Delineation	
	Applicant:			
	Mary Anne		Antonellis	
	a. First Name		b. Last Name	
	Town of Shu	ıtesbury		
	c. Organization			
	-	lle Road, PO Box 256		
	d. Mailing Addr			
	Shutesbury		MA	01072
	e. City/Town		f. State	g. Zip Code
	a. First Name		b. Last Name	
	c. Organization	1		
	d. Mailing Addr	ress		
	e. City/Town		f. State	g. Zip Code
	Project Loca	ation:		
	66 Leverett	Road	Shutesbury	01072
	a. Street Addre	ess	b. City/Town	c. Zip Code
	Мар О		Lot 32	
	d. Assessors M	lap/Plat Number	e. Parcel/Lot Num	ber
	Latitude and	d Longitude	42.45094N	72.41611W
	(in degrees,	minutes, seconds):	f. Latitude	g. Longitude
	Datas	9/30/2022	03/09/2023	03/10/2023
	Dates:	a. Date ANRAD filed	b. Date Public Hearing Close	c. Date of Issuance
ı	Title and Da	te (or Revised Date if appl	icable) of Final Plans and Oth	er Documents:
iہ			Road Shutesbury, Massachuse	• ` ` `
ıy		3-2 prepared by Fuss and (revised)
1a		elineation Overview 66 Lev Figure 2 prepared by Fuss		February 2023 (last revised)

Town of Shutesbury

1.

Conservation Commission

Form 4B - Order of Resource Area **Delineation** Shutesbury General Wetlands Protection Bylaw

Provid	ded by MassDEP:
2	286-0297
1	MassDEP File Number
6	DEP Transaction Number
	Shutesbury
(Citv/Town

B. Order of Delineation

The	Conse	ervation Commission has determined the following (check whichever is applicable):
а. [ccurate: The boundaries described on the referenced plan(s) above and in the Abbreviated of Resource Area Delineation are accurately drawn for the following resource area(s):
	1.	☐ Bordering Vegetated Wetlands
	2.	Other resource area(s), specifically:
	a.	
b. [Co	odified: The boundaries described on the plan(s) referenced above, as modified by the onservation Commission from the plans contained in the Abbreviated Notice of Resource rea Delineation, are accurately drawn from the following resource area(s):
	1.	⊠ Bordering Vegetated Wetlands
	2.	○ Other resource area(s), specifically:
	a.	PLEASE SEE ATTACHED FINDINGS
с. [No	accurate: The boundaries described on the referenced plan(s) and in the Abbreviated of Resource Area Delineation were found to be inaccurate and cannot be confirmed the following resource area(s):
	1.	☐ Bordering Vegetated Wetlands
	2.	Other resource area(s), specifically:
	3.	☐ The boundaries were determined to be inaccurate because:

Town of Shutesbury

Conservation Commission

Form 4B – Order of Resource Area Delineation

Shutesbury General Wetlands Protection Bylaw

MassDEP File Number

eDEP Transaction Number

Shutesbury

City/Town

Provided by MassDEP: 286-0297

C. Findings

This Order of Resource Area Delineation determines that the boundaries of those resource areas noted above, have been delineated and approved by the Commission and are binding as to all decisions rendered pursuant to the Shutesbury General Wetlands Protection Bylaw and its regulations. This Order does not, however, determine the boundaries of any resource area or Buffer Zone to any resource area not specifically noted above, regardless of whether such boundaries are contained on the plans attached to this Order or to the Abbreviated Notice of Resource Area Delineation.


This Order must be signed by a majority of the Conservation Commission. The Order must be sent by certified mail (return receipt requested) or hand delivered to the applicant. A copy also must be mailed or hand delivered at the same time to the appropriate DEP Regional Office (see http://www.mass.gov/eea/agencies/massdep/about/contacts/find-the-massdep-regional-office-for-your-city-or-town.html).

Town of Shutesbury Conservation Commission	Provided by MassDEP: 286-0297
	MassDEP File Number
Form 4B – Order of Resource Delineation	ober Transaction Tambel
Shutesbury General Wetlands Protection	Sincesbury
E. Signatures	03/10/2023
See attached Certificate of Vote authorize Please indicate the number of members who will s	ian this form
Miriam DeFant	Mary David 1. Number of Signers
Signature of Conservation Commission Member Robin Harrington	Signature of Conservation Commission Member Scott Kahan
Signature of Conservation Commission Member Beth Willson	Signature of Conservation Commission Member
Signature of Conservation Commission Member	Signature of Conservation Commission Member
Signature of Conservation Commission Member	
This Order is valid for three years from the date	e of issuance.
	Resource Area Delineation, this Order does not extend which expires on 03/10/2026 unless extended in writing
This Order is issued to the applicant and the prope	erty owner (if different) as follows:
2. By hand delivery on	3. By certified mail, return receipt requested on
03/10/2023	
a. Date	a. Date

CERTIFICATE OF VOTE AUTHORIZING SIGNATURES PURSUANT TO M.G.L. c.110G

On May 14, 2020, the Shutesbury Conservation Commission met in open session through publicly accessible video-conference software, pursuant to the "Order Suspending Certain Provisions of the Open Meeting Law, G.L. c. 30A, §20," issued by Governor Charles D. Baker on March 12, 2020. At this duly held meeting, the following action was taken:

Motion: Shutesbury Conservation Commission hereby recognizes and accepts the provisions of M.G.L. c.110G regarding electronic signatures and that its members will henceforth execute documents either with electronic signatures or with wet ink signatures and that both will carry the same legal weight and effect. Motion was seconded.



Roll Call vote:



Shutesbury Conservation Commission Attachment for ORAD at 66 Leverett Road (Lot O-32) DEP File # 286-0297

Date: March 10, 2023 Lot: Map 0, LOT 32

Applicant: Town of Shutesbury
Landowners: Town of Shutesbury

These findings are based on the figure set "Wetland Flag Locations 66 Leverett Road Shutesbury, Massachusetts" Figure 3-1 and 3-2 and "Wetland Delineation Overview 66 Leverett Road Shutesbury, Massachusetts" Figure 2 prepared by Fuss and O'Neill February 2023 (last revised).

- 1. This Order of Resource Area Delineation is hereby issued pursuant to the Conservation Commission's jurisdiction over Resource Areas as defined by the Wetlands Protection Act (MGL Chapter 131, § 40), the Wetlands Protection Act Regulations (310 CMR 10.00), and Shutesbury General Wetlands Protection Bylaw and Bylaw Regulations.
- 2. The Shutesbury Conservation Commission approves the boundaries of Bordering Vegetated Wetlands depicted on the final site plans "Wetland Flag Locations 66 Leverett Road Shutesbury, Massachusetts" Figure 3-1 and 3-2 prepared by Fuss and O'Neill February 2023 (last revised).
- 3. The Commission does not approve any Protected Resource Area boundaries located outside of the depicted ANRAD Review Area boundary on the final site plans.
- 4. The following findings concern jurisdictional areas protected by both the Massachusetts Wetlands Protection Act and the Shutesbury General Wetland Protection Bylaw ("the Bylaw":
 - The Commission approves the boundary of 100-foot Buffer Zones within the ANRAD Review Area boundary, including the no-contest Buffer Zone boundaries, but <u>excluding</u> the Buffer Zone boundary associated with the BVW boundary between flags wf 3a-114 and wf 3a-115. The BVW boundary between flags wf 3a-114 and wf 3a-115 has not been established, reviewed, and approved. Therefore, the associated Buffer Zone boundary has not been established, reviewed, and approved. Any Buffer Zone for this Resource Area depicted on the site plan is not approved.
 - The Commission approves the boundary of the Bordering Vegetated Wetland BVW 1 demarcated by flags wf 1a-100 through and including wf 1a-133.
 - The Commission approves the boundary of the Bordering Vegetated Wetland BVW 2 extending from the property lines and demarcated by flags wf 2a-101 through and including wf 2a-105.
 - The Commission finds that the BVW 2 has been impacted by the unauthorized, post-1965 and 1972 placement of a fill pile within the BVW as noted on Page 5 of the "Massachusetts Inland Resource Area Delineation Report" prepared by Fuss and O'Neill (last revised February 1, 2023).

- The Commission finds that the BVW 2 must be restored.
- The Commission approves the boundary of the Bordering Vegetated Wetland BVW 3 extending from the property lines and demarcated by flags wf 3b-101 through and including wf 3b-113 (joins wf 3a-100); wf 3a-100 through and including wf 3a-114; and wf 3a-115 through and including wf 3a-117. The Commission does <u>not</u> approve the BVW boundary between flags wf 3a-114 and wf 3a-115.
- The Commission finds that the BVW proximal to flags wf 3a-114 and wf 3a-115 has been impacted by the unauthorized, post-1965 and 1972 placement of fill within the BVW.
- The Commission finds that the BVW proximal to flags wf 3a-114 and wf 3a-115 must be restored and the BVW boundary established per 310 CMR 10.55(2)(c)3.
- The Commission finds that Isolated Vegetated Wetlands (IVWs) 4, 5, 6 and 7 do not meet the definition of Isolated Land Subject to Flooding under 310 CMR 10.57(2)(b)1.
- 5. The following findings concern the jurisdictional areas protected by the Shutesbury General Wetland Protection Bylaw:
 - The Commission approves the boundary of 100-foot Buffer Zones within the ANRAD Review Area boundary, including the no-contest Buffer Zone boundaries, but **excluding** the Buffer Zone boundary associated with the BVW boundary between flags wf 3a-114 and wf 3a-115. The BVW boundary between flags wf 3a-114 and wf 3a-115 has not been established, reviewed, and approved. Therefore, the associated Buffer Zone boundary has not been established, reviewed, and approved.
 - Buffer Zones are protected as Resource Areas under the Bylaw.
 - The Commission finds that Isolated Vegetated Wetlands (IVWs) 4, 5, 6 and 7 do not meet the size criteria for protection as Isolated Vegetated Wetlands under the Shutesbury Wetlands Bylaw Regulations.
 - Subsurface lakes, rivers, ponds, and streams are protected as Resource Areas under the Bylaw. The boundaries of subsurface lakes, rivers, ponds, and streams have not been delineated and are not approved by the Commission.
 - The areas within 100 feet of subsurface lakes, rivers, ponds, and streams are protected as Resource Areas under the Bylaw. The boundaries of areas within 100 feet of subsurface lakes, rivers, ponds, and streams have not been delineated and are not approved by the Commission.
 - If a Notice of Intent is required for work within the ANRAD Review Area boundary, the applicant must submit a site plan depicting all jurisdictional Resource Area boundaries under the Bylaw, those approved under this ORAD and those present but not reviewed and approved under this ORAD.
- 6. A southeasterly portion of the ANRAD Review Area is located within a mapped Outstanding Resource Area associated with the Quabbin Reservoir Public Water Supply Watershed.